





report date: 2024-03-29

### General information

Make	LAND ROVER
Model	FREELANDER SD4 GS
Colour	Black
Year of manufacture	2014
Top speed	118 mph
0 - 100 km/h	9.5 seconds
0 - 60 mph	8.7 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	140 kW / 191 HP / 190 BHP
Max. torque	420 Nm at 1.750 rpm
Engine capacity	2.179 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	40.4 mpg
CO2 emission	185 g/km
CO2 label	I



CarCheck.co.uk page 1/12



LY63BZT

report date: 2024-03-29

## Internet history


### Entry 1


Date 2021-08-04

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-10-30
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	11
Total items failed	1

MOT #10	2023-10-31 11:06
MOT test number	911147144835
Result	✓ Passed
Next expiry date	2024-10-30

MOT #9	2022-10-12 09:15
MOT test number	523452591488
Result	<b>✓</b> Passed

MOT #8	2021-10-18 10:52
MOT test number	933952079290
Result	✓ Passed

MOT #7		2020-10-26 14:22
MOT test	number	184076018706
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)	))
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



MOT #6 2019-10-16 00:44

**MOT test number** 127475954217

Result \rightarrow Passed

MOT #5 2019-01-15 14:11

**MOT test number** 978407969771

Result 

✓ Passed

MOT #4 2019-01-15 10:30

**MOT test number** 414180092740

**Result** X Failed

**Advice** Nearside Front tyre has nail in it

**DANGEROUS** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Advice** Front pads look low

MOT #3 2018-01-09 11:31

MOT test number 355010467917

Result \sqrt{Passed}

**MOT #2** 2017-01-12 13:24

**MOT test number** 439174489126

CarCheck.co.uk page 4/12



LY63BZT

report date: 2024-03-29

MOT #1 2017-01-11 15:58

**MOT test number** 421278992606

Result X Failed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Rear Nail in tyre

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	30 October 2024
Full MOT history	See MOT history

### Tax calculation

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date
Category
Type

Damage 2

Date

Category

**Type** 



#### Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



### Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e mier meerty	
For how long did the current and previous owner(s) have this LAND ROVER? How many o ROVER have? Check it in the premium report and see all owner registrations. Download to	
***************************************	
***************************************	
THE PERSON NAMED IN COLUMN TO THE PE	
	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	
Number of plates	,
Current registration	UK ZIS
Plate since	
Current registration	RIV.
Plate since	
	More info >

CarCheck.co.uk page 9/12



### Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



## Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-01-16
Last registration	2023-10-31
Complete history	See info



Registration #1	2014-01-16	18 mi
Registration #2	2017-01-11	46.175 mi
Registration #3	2017-01-12	46.176 mi
Registration #4	2018-01-09	59.176 mi
Registration #5	2019-01-15	69.066 mi
Registration #6	2019-01-15	69.070 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 11/12



## Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	2005 mm
Height	1740 mm
Length	4500 mm
Wheel base	2660 mm
Kerb weight	1745 kg
Max. allowed weight	2505 kg

## Additional information

Fuel tank capacity	68 I
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	DZ784181354224DT

CarCheck.co.uk page 12/12