





report date: 2024-03-28

### General information

Make	PEUGEOT
Model	208 ACTIVE
Colour	Orange
Year of manufacture	2017
Top speed	111 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	82 BHP
Max. torque	118 Nm at 2.750 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	104 g/km
CO2 label	В



CarCheck.co.uk page 1/13



report date: 2024-03-28

## Internet history

#### Entry 1

Date 2021-02-03

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

## **MOT** history

MOT expiry date	2025-04-04
MOT pass rate	56 %
MOT passed	5
Failed MOT tests	4
Total advice items	18
Total items failed	10

MOT #9	2024-04-05 09:41
MOT test number	191050620400
Result	✓ Passed
Next expiry date	2025-04-04
Minor (b) (i))  Nearside Registration plate lamp inoperative in the case of multiple lamps	s or light sources (4.7.1
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

**MOT #8** 2024-03-13 17:20 **MOT** test number 213988531240 Result **X** Failed **Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt **Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii)) Emissions unable to be completed suspect induction leak causing emissions to fail (8.2.1.2 (d)) Fail **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))Fail Front Bumper damaged and likely to cause injury when grazed or contacted (6.1.4 (a) (i)) Fail Exhaust emissions likely to be affected by an induction leak vehicle hunting and vac leak noise can be heard (emissions effected) (8.2.2.1 (b)) **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Minor Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #7	2023-03-15 16:11
MOT test number	529908954751
Result	✓ Passed
MOT #6	2023-03-15 16:11
MOT test number	746974261332
Result	<b>X</b> Failed
Pass with rectification	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT test number

Result

Advice Front Brake disc worn, but not excessively both sides (1.1.14 (a) (i))

Advice Offside Front Road wheel slightly distorted inner and outer (5.2.2 (c) (i))

**MOT #4** 2022-03-10 12:58 **MOT** test number 246555264405 Result **X** Failed Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii)) Advice Offside Front Road wheel slightly distorted inner and outer (5.2.2 (c) (i)) Advice Front Brake disc worn, but not excessively both sides (1.1.14 (a) (i)) Offside Front Headlamp aim not tested (4.1.2 (b)) Fail Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Fail (5.2.3 (d) (i))

MOT #3

MOT test number

703495673769

Result

✓ Passed

MOT #2

MOT test number

809890328405

Result

Advice Nearside Rear Nail in tyre 2 nails in tyre

Advice Offside Front Nail in tyre

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #1 2020-09-10 13:34

**MOT test number** 159237410268

**Result** X Failed

**Advice** Nearside Rear Nail in tyre 2 nails in tyre

**Pass with rectification** Offside Front Headlamp aim projected beam image is obviously incorrect bulb fitted wrong way (4.1.2 (c))

**Advice** Offside Front Nail in tyre

CarCheck.co.uk page 6/13



report date: 2024-03-28

# Tax & MOT check



Tax status	Valid until 1 May
Days left	367
MOT expiry date	4 April 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner	history

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		GEOT
THE PARTY OF THE P		
***************************************		
	More info	>
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-28

#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2017-08-14
Last registration	2024-04-05
Complete history	See info



Registration #1	2017-08-14	11 mi
Registration #2	2020-09-10	26.442 mi
Registration #3	2020-09-10	26.442 mi
Registration #4		11.117 es
Registration #5	2021-02-17	26.518 mi
Registration #6	2022-03-10	36.655 mi
Registration #7		11.177 mi
Registration #8		11.177 es
Registration #9		11.177 mi
Registration #10		11.117 es
Registration #11		71.777 mg

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	88%
Children	78%
Pedestrian	61%
Safety systems	83%
Overall rating	80%
Video	see crash video



# Dimensions & weight

Width	1739 mm
Height	1460 mm
Length	3973 mm
Wheel base	2538 mm
Kerb weight	975 kg
Max. allowed weight	1546 kg

## Additional information

Fuel tank capacity	50	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page	e 13/13

Number of axles 2

Engine number B2170104976