





report date: 2024-03-29

General information

Make	FIAT
Model	BRAVO SPORT TJET
Colour	Grey
Year of manufacture	-
Top speed	132 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	206 Nm at 2.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.8 mpg



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1


Date 2021-09-03

Pictures 18

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT #14 2022-10-06 10:09

MOT test number 308196174814

Result

✓ Passed

Next expiry date 2023-10-05

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Rear Exhaust mounting is broken

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Rear Registration plate lamps low intensity

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #13 2022-09-27 09:45

MOT test number 231861848795

Result X Failed

MAJOR Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MAJOR Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MAJOR Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Rear Registration plate lamps low intensity

MAJOR Nearside Headlamp insecure (4.1.1 (c))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MAJOR Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MAJOR Offside Front Position lamp not working (4.2.1 (a) (ii))

MAJOR Offside Front Road wheel badly distorted rim (5.2.2 (c) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MAJOR Offside Headlamp insecure (4.1.1 (c))

Advice Rear Exhaust mounting is broken

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #12 2021-09-22 13:42

MOT test number 196422553731

Result ✓ Passed

MOT #11 2020-09-19 08:49

MOT test number 150228478519

Advice Offside Front Tyre worn close to legal limit/worn on edge DRIVERS - 2.5MM (5.2.3 (e))

MOT #10 2019-09-18 11:56

MOT test number 579912937637

Result Passed

Minor Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #9 2018-09-19 09:30

MOT test number 114153486713

Result Passed

Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

Minor Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #8 2017-09-20 09:31

MOT test number 907531434440

Result

Passed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #7 2016-09-20 10:47

MOT test number 457840745655

Result
✓ Passed

CarCheck.co.uk page 4/11



MOT test number

Result

AK57ZBO

report date: 2024-03-29

305571072446

✓ Passed

MOT #6		2015-09-22 09:17
MOT test	number	401415799004
Result		✓ Passed
MOT #5		2014-09-22 11:11
MOT test	number	365115664278
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Nearside rear tyre scrubbed on sidewall	
Notice	Child seat fitted not allowing full inspection of adult belt	
MOT #4		2013-09-27 09:58
MOT test	number	895580273209
Result		✓ Passed
MOT #3		2012-09-27 14:47

MOT #2	2011-09-27 11:21
MOT test number	395230571252

Result ✓ Passed

MOT #1	2010-09-27 09:48
MOT test number	332640270263
Result	✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



AK57ZBO report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



AK57ZBO report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report		e?

	More info	>
Plate changes See in this check if this FIAT had different number plates.		
See in this eneck is that had amerene names places.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



AK57ZBO report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte at Info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-09-27
Last registration	2022-10-06
Complete history	See info



Registration #1	2007-09-27	13 mi
Registration #2	2010-09-27	21.331 mi
Registration #3	2011-09-27	27.143 mi
Registration #4	2012-09-27	33.131 mi
Registration #5	2013-09-27	38.795 mi
Registration #6	2014-09-22	43.979 mi
Registration #7	2015-09-22	47.718 mi
Registration #8	2016-09-20	51.949 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.77 66
Registration #12		11.777 es
Registration #13		9.77 66
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		10.777 mg

More info >

CarCheck.co.uk page 10/11



AK57ZBO report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1792 mm
Height	1498 mm
Length	4336 mm
Wheel base	2600 mm
Kerb weight	1275 kg
Max. allowed weight	1785 kg

Additional information

Fuel tank capacity	58 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11,

Number of axles 2
Engine number 1164652