



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	CLK CLK350 AVANTGARDE
Colour	Black
Year of manufacture	2005
Top speed	155 mph
0 - 60 mph	6.7 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	268 BHP
Max. torque	350 Nm at 3.000 rpm
Engine capacity	3.498 cc
Cylinders	6
Fuel type	Petrol
Consumption city	19.3 mpg
Consumption extra urban	36.7 mpg
Consumption combined	27.7 mpg
CO2 emission	241 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-06-30
Pictures	13
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-10
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	15
Total items failed	11

MOT #20	2023-07-28 08:57
MOT test number	420197675780
Result	✓ Passed
Next expiry date	2024-08-10
Advice	Rear brake pads wearing low-
Advice	Rear axle corroded-front brake discs corroded/pitted-o s f tyre edges worn-rear tyres worn low-both front brake pipes corroded-rear brake discs corroded/pitted-

MOT #19	2022-08-08 11:22
MOT test number	729506185254
Result	✓ Passed
Advice	Both front tyres edges wearing low-rear axle corroded-

MOT #18	2021-07-30 11:26
MOT test number	401499639243
Result	✓ Passed
Advice	Both rear tyres on limit-o/s/f and n/s/f/ coil springs corroded-

MOT #17	2020-08-11 09:12
MOT test number	996723579401
Result	✓ Passed



MOT #16	2019-05-01 11:05
MOT test number	722378400588
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #15	2019-05-01 11:05
MOT test number	909208255714
Result	✗ Failed
Pass with rectification	Windscreen washer not working (3.5 (a))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #14	2018-05-01 15:59
MOT test number	484971127186
Result	✓ Passed
Advice	Vehicle fitted with full length under body trays obscuring underside from inspection

MOT #13	2018-04-30 11:09
MOT test number	759104667393
Result	✗ Failed
Fail	Nearside Front front brake excessively fluctuating (3.7.B.3)
Fail	Nearside Brake pipe excessively corroded front to rear (3.6.B.2c)
Advice	Nearside Front Windscreen wiper not clearing the windscreen effectively
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively blade torn (8.2.2)
Fail	Offside Front front brake excessively fluctuating (3.7.B.3)
Fail	Offside Brake pipe excessively corroded front to rear (3.6.B.2c)
Advice	Vehicle fitted with full length under body trays obscuring underside from inspection

**MOT #12** 2017-11-22 17:17**MOT test number** 581393931040**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Fail** Front front brake excessively fluctuating both (3.7.B.3)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear exhaust heat shield not secure**Fail** Rear Brake pipe excessively corroded both to rear flexis (3.6.B.2c)**MOT #11** 2017-03-30 11:04**MOT test number** 114398044220**Result** ✓ Passed**Advice** Offside Front tyre worn low on outer edge**MOT #10** 2016-03-22 12:00**MOT test number** 503585701501**Result** ✓ Passed**MOT #9** 2015-03-13 13:02**MOT test number** 839862375049**Result** ✓ Passed**MOT #8** 2014-03-25 09:06**MOT test number** 207904784021**Result** ✓ Passed

**MOT #7** 2014-03-24 14:30**MOT test number** 667003284015**Result** ✗ Failed**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Fail** Offside Rear coil spring broken (2.4.C.1a)**MOT #6** 2013-03-15 12:02**MOT test number** 778444873060**Result** ✓ Passed**MOT #5** 2012-03-24 11:48**MOT test number** 156874882454**Result** ✓ Passed**MOT #4** 2011-03-25 12:41**MOT test number** 907644381075**Result** ✓ Passed**Advice** Brake pad(s) wearing thin (3.5.1g)**Advice** Brake pipe slightly corroded (3.6.B.2c)**MOT #3** 2010-02-04 16:40**MOT test number** 172465430095**Result** ✓ Passed**MOT #2** 2009-02-09 14:30**MOT test number** 133460249042**Result** ✓ Passed



MOT #1	2008-11-25 11:29
MOT test number	664280638399
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
10 August 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	10 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 LM55EXD
Plate since	2019-06-29
Current registration	 LM55EXD
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-12-22
Last registration	2023-07-28
Complete history	See info



Registration #1	2005-12-22	6 mi
Registration #2	2008-11-25	30.293 mi
Registration #3	2009-02-09	30.304 mi
Registration #4	2010-02-04	44.917 mi
Registration #5	2011-03-25	52.740 mi
Registration #6	2012-03-24	60.249 mi
Registration #7	2013-03-15	70.440 mi
Registration #8	2014-03-24	80.774 mi
Registration #9	2014-03-25	80.774 mi
Registration #10	2015-03-13	91.302 mi
Registration #11	2016-03-22	96.635 mi
Registration #12	2016-03-22	96.635 mi
Registration #13	2016-03-22	96.635 mi
Registration #14	2016-03-22	96.635 mi
Registration #15	2016-03-22	96.635 mi
Registration #16	2016-03-22	96.635 mi
Registration #17	2016-03-22	96.635 mi
Registration #18	2016-03-22	96.635 mi
Registration #19	2016-03-22	96.635 mi
Registration #20	2016-03-22	96.635 mi
Registration #21	2016-03-22	96.635 mi
Registration #22	2016-03-22	96.635 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2690 mm
Kerb weight	1735 kg
Max. allowed weight	2190 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27296030175281