





report date: 2024-03-28

General information

Make	VAUXHALL
Model	COMBO 2000 L1H1 CDTI SPORTIVE
Colour	White
Year of manufacture	2014
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Engine capacity	1.248 сс
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	133 g/km
CO2 label	Е



CarCheck.co.uk page 1/11



MOT history

MOT expiry date	2024-05-13
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	9
Total items failed	6

MOT #9	2023-05-02 10:19
MOT test number	189704086816
Result	✓ Passed
Next expiry date	2024-05-13
Advice Nearside Front Top mounting - slight play.	

MOT #8	2022-04-30 11:34
MOT test number	325072609754
Result	✓ Passed

MOT #7	2022-04-30 09:27
MOT test number	461173685375
Result	X Failed
Fail Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i)))
Fail Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a)	(i))

MOT #6		2021-05-14 12:06
MOT test	number	360833185942
Result		✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge offside/nearside (5.2.3 (e))	
Advice	General corrosion at suspension components	

CarCheck.co.uk page 2/11



Advice

FL64ZVU report date: 2024-03-28

MOT #5 2020-03-09 16:21 **MOT test number** 448287859078 Result ✓ Passed MOT #4 2019-03-14 15:40 **MOT** test number 867169192898 Result ✓ Passed MOT #3 2018-03-20 10:38 **MOT** test number 247853982152 Result ✓ Passed MOT #2 2017-03-15 14:23 805801514004 **MOT test number** Result ✓ Passed **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Exhaust has a minor leak of exhaust gases (7.1.2)

CarCheck.co.uk page 3/11



MOT #1 2017-03-15 12:42

MOT test number 295488822295

Result X Failed

Fail Nearside Side repeater not working (1.4.A.2c)

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Registration plate lamp not working (1.1.C.1d)

Fail Nearside Stop lamp not working (1.2.1b)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Exhaust has a minor leak of exhaust gases (7.1.2)

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	13 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category

Type

Damage 2

Date

Category

Type



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

Owner History	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlo here.	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	UK
Plate since	
Current registration	OK OK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-09-30
Last registration	2023-05-02
Complete history	See info



Registration #1	2014-09-30	24 mi
Registration #2	2017-03-15	34.402 mi
Registration #3	2017-03-15	34.402 mi
Registration #4	2018-03-20	43.524 mi
Registration #5	2019-03-14	49.803 mi
Registration #6		
Registration #0		
Registration #7		7.77
		11.77 m
Registration #7		11.77 mi 11.77 mi 11.77 mi

More info >

CarCheck.co.uk page 10/11



Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	263A20005566978 LN9

CarCheck.co.uk page 11/11