





report date: 2024-03-29

General information

| Make | FIAT |
|---------------------|-----------------|
| Model | FULLBACK LX DCB |
| Colour | Black |
| Year of manufacture | 2016 |
| Top speed | 111 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 180 BHP |
|----------------------|---------------------|
| Max. torque | 430 Nm at 2.500 rpm |
| Engine capacity | 2.442 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption combined | 42.8 mpg |
| CO2 emission | 173 g/km |
| CO2 label | Н |



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2022-07-05

Pictures 4

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



| B 4 | \sim $-$ | | |
|-------|-------------|------|--------|
| 10.71 | $^{\prime}$ | hic | tory |
| 101 | C I | 1115 | I OI V |
| | • | | , |

| MOT expiry date | 2024-07-24 |
|--------------------|------------|
| MOT pass rate | 83 % |
| MOT passed | 5 |
| Failed MOT tests | 1 |
| Total advice items | 7 |
| Total items failed | 1 |

| MOT #6 | | 2023-07-25 07:53 |
|--|--|------------------|
| MOT test | number | 525274365472 |
| Result | | ✓ Passed |
| Next expi | ry date | 2024-07-24 |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | | |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| | MOT #5 | | | 2023-07-25 07:53 |
|---|---|-----------------|---|------------------|
| | MOT test | number | | 891387438199 |
| ١ | Result | | | 🗙 Failed |
| | Pass wit | h rectification | Windscreen washer provides insufficient washer liquid (3.5 (a)) | |
| | Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | | | |
| | Advice | Nearside Rear T | yre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #4 | 2022-06-22 17:25 |
|-----------------|------------------|
| MOT test number | 923284918824 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2021-08-30 12:41 |
| MOT test number | 811546317011 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



MOT #2 2020-09-21 13:06 **MOT test number** 193727560996 Result ✓ Passed MOT #1 2019-09-02 12:56 **MOT test number** 661881024381 Result Passed Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Front brake discs badly corroded. Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 October |
|------------------|-----------------------|
| Days left | 154 |
| MOT expiry date | 24 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 39 |
|---------------------------|------------|
| Standard rate (12 months) | £ 275,00,- |
| Standard rate (6 months) | £ 151,25,- |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report $\underline{\mathbf{k}}$ | |
|--|-------------|
| | |
| HARMAN CO. C. | |
| | |
| | |
| ********** | |
| *************************************** | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this FIAT had different number plates. | |
| Number of plates | , |
| Current registration | NIE UK |
| Plate since | |
| Current registration | NK NK |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 8 |
| First mileage registration | 2016-09-22 |
| Last registration | 2023-07-25 |
| Complete history | See info |



| Registration #1 | 2016-09-22 | 10 mi |
|-----------------|------------|-----------|
| Registration #2 | 2019-09-02 | 18.847 mi |
| Registration #3 | 2020-09-21 | 27.099 mi |
| Registration #4 | 2021-08-30 | 35.808 mi |
| Registration #5 | | 11.777 es |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |

More info >

CarCheck.co.uk page 10/11



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Additional information

| Fuel delivery | Direct Injection |
|-----------------|------------------|
| Number of doors | 4 |
| Number of seats | 5 |
| Engine number | UAS4088 |

CarCheck.co.uk page 11/11