



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX35 GDI SE NAV BLUE DRIVE
Colour	Grey
Year of manufacture	2015
Top speed	111 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	133 BHP
Max. torque	165 Nm at 4.800 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	44.1 mpg
CO2 emission	149 g/km
CO2 label	F









Internet history

Entry 1

Date	2022-06-08
Pictures	19
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-03-01
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	15
Total items failed	0

MOT #10	2024-02-28 11:44
MOT test number	509801877164
Result	✓ Passed
Next expiry date	2025-03-01

MOT #9	2023-02-23 11:09
MOT test number	327291127880
Result	✓ Passed

MOT #8	2023-02-22 09:34
MOT test number	685132361472
Result	✗ Failed
<b>MAJOR</b> Nearside Direction indicator with a multiple light source more than 1/2 not functioning (4.4.1 (a) (ii))	
<b>MAJOR</b> Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	

MOT #7	2022-03-01 08:39
MOT test number	887252074366
Result	✓ Passed
<b>Advice</b> Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>Advice</b> Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

**MOT #6** 2022-02-28 10:07**MOT test number** 125084531898**Result** ✗ Failed**MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #5** 2021-03-02 17:20**MOT test number** 523886698645**Result** ✓ Passed**MOT #4** 2020-11-17 10:07**MOT test number** 708918508338**Result** ✓ Passed**MOT #3** 2019-05-23 09:57**MOT test number** 266055775023**Result** ✓ Passed**Advice** Central Front PARKING BRAKE TRAVEL LONG



MOT #2 2019-05-17 11:53

MOT test number 874001572392

Result ✗ Failed

**Advice** Rear Brake disc worn, but not excessively \*\*\*STRONG ADVISE\*\*\* (1.1.14 (a) (i))

**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #1 2018-05-17 09:48

MOT test number 780816611477

Result ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
1 March 2025

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	32
<b>MOT expiry date</b>	1 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-05-29
Last registration	2024-02-28
Complete history	<a href="#">See info</a>



Registration #1	2015-05-29	19 mi
Registration #2	2018-05-17	33.860 mi
Registration #3	2019-05-17	38.742 mi
Registration #4	2019-05-23	38.749 mi
Registration #5	2020-11-17	41.357 mi
Registration #6	2021-03-02	41.481 mi
Registration #7	2022-05-29	41.577 mi
Registration #8	2023-05-29	41.577 mi
Registration #9	2023-05-29	41.577 mi
Registration #10	2023-05-29	41.577 mi
Registration #11	2023-05-29	41.577 mi
Registration #12	2024-02-28	41.577 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1427 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number

G4FDFZ518175