





report date: 2024-03-29

General information

Make	NISSAN	
Model	PATHFINDER DCI AVENTURA E4	
Colour	Silver	
Year of manufacture	2007	
Top speed	109 mph	
Gearbox	6 speed Manual	

Engine & fuel consumption

Power	169 BHP
Max. torque	403 Nm at 2.000 rpm
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel
Consumption city	23.5 mpg
Consumption extra urban	33.2 mpg
Consumption combined	28.8 mpg
CO2 emission	264 g/km
CO2 label	M



CarCheck.co.uk page 1/14



report date: 2024-03-29

Internet history

Entry 1

Date 2022-04-02

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/14



BT07V0U report date: 2024-03-29

MOT history

MOT expiry date	2025-04-25
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	22
Total items failed	15

MOT #18		2024-04-26 14:34
MOT test	number	779745063563
Result		✓ Passed
Next expiry date 2025-04-25		
Minor Nearside Front Window excessively tinted but not adversely affecting driver's view (3.2 (b) (i))		
Minor Nearside Front Window excessively tinted but not adversely affecting driver's view (3.2 (b) (i))		
Minor Offside Front Window excessively tinted but not adversely affecting driver's view (3.2 (b) (i))		

MOT #17	2024-04-26 12:03
MOT test number	466914523709
Result	X Failed
Minor Nearside Front Window excessively tinted but not adversely affecting d	river's view (3.2 (b) (i))
Fail Electronic stability control warning lamp indicates a fault (7.12 (e))	
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	
Minor Offside Front Window excessively tinted but not adversely affecting driv	ver's view (3.2 (b) (i))
Fail Electronic stability control switch not functioning correctly (7.12 (d))	
Fail Brake lever has insufficient reserve travel (1.1.2 (a))	

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #16 2024-04-05 09:09

MOT test number 822431934963

Result X Failed

Fail Electronic stability control warning lamp indicates a fault (7.12 (e))

Fail Central Exhaust emissions likely to be affected by an exhaust leak (8.2.2.1 (b))

Fail Emissions unable to be completed Excessive leaks (8.2.2.2 (e))

Fail Central Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))

Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Fail Offside Front Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))

Fail Front Exhaust emissions likely to be affected by an exhaust leak Flexi (8.2.2.1 (b))

MOT #15 2023-03-30 14:41

MOT test number 937058425623

Result \(\sqrt{Passed} \)

MOT #14 2023-03-27 07:58

MOT test number 143783065788

Result X Failed

Fail Offside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))

Fail Horn not working (7.7 (a))

MOT #13 2022-04-05 15:57

MOT test number 960181165887

Result

Passed

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #12 2022-03-25 17:33

MOT test number 390522470295

Result × Failed

Fail Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #11 2021-01-04 13:58

MOT test number 834312860210

Result
✓ Passed

MOT #10 2019-10-14 10:03

MOT test number 131738569070

Result ✓ Passed

MOT #9 2018-09-15 10:05

MOT test number 622271592648

Result ✓ Passed

MOT #8 2017-09-22 11:55

MOT test number 785999518298

MOT #7 2016-09-16 13:31

MOT test number 820122250783

Result

Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #6 2015-09-29 14:40

MOT test number 729690639007

Result ✓ Passed

Advice Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)

Advice Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)

Advice Front Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #5 2014-08-29 15:24

MOT test number 209051444249

Result ✓ Passed

Notice N/s parking brake not as efficient as o/s

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Notice Headlamp masks/converters fitted

Notice Movement in both front lower ball joints.

Advice Exhaust has a minor leak of exhaust gases (7.1.2)

Notice Both front tyres, treads low outer edges.

MOT #4 2013-09-04 09:39

MOT test number 636357643227

Advice Offside Outer Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

Advice Nearside Outer Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #3

MOT test number

499650652288

Result

Advice Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

MOT test number

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

Notice Nail in nearside rear tyre

Advice Rear Brake pad(s) wearing thin (3.5.1g)

 MOT #1
 2010-07-02 15:43

 MOT test number
 634593880178

 Result
 ✓ Passed

CarCheck.co.uk page 7/14



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	25 April 2025
Full MOT history	See MOT history

Tax calculation

Waltisla slave	40
Vehicle class	49
Band	М
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.		
	More info	
Plate changes		
See in this check if this NISSAN had different number plates.		
Number of plates		,
Current registration	NK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	•

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-06-29
Last registration	2024-04-26
Complete history	See info



Registration #1	2007-06-29	27 mi
Registration #2	2010-07-02	37.818 mi
Registration #3	2011-10-24	53.139 mi
Registration #4	2012-09-06	59.474 mi
Registration #5	2013-09-04	71.470 mi
Registration #6	2014-08-29	78.536 mi
Registration #7	2015-09-29	85.097 mi
Registration #8	2016-09-16	96.607 mi
Registration #9	2017-09-22	105.516 mi
Registration #10	2018-09-15	113.322 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		9.70 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		71.777 es

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1850 mm
Height	1783 mm
Length	4740 mm
Wheel base	2850 mm
Kerb weight	2132 kg
Max. allowed weight	2880 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 14/14

Number of axles 2

Engine number 859871