




report date: 2024-03-28

General information

Make	KIA
Model	MAGENTIS LS
Colour	Black
Year of manufacture	2008
Top speed	129 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	142 BHP
Max. torque	187 Nm at 4.250 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	46.3 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-12-16
Pictures	3
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-03
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	25
Total items failed	10

MOT #18	2023-12-07 13:43
MOT test number	963911737440
Result	✓ Passed
Next expiry date	2025-01-03

MOT #17	2022-12-16 14:19
MOT test number	953287024893
Result	✓ Passed

- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Steering column top bearing slightly worn (2.2.2 (b))
- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Front Exhaust mounting defective (6.1.2 (a))

MOT #16	2022-01-04 10:25
MOT test number	955654350826
Result	✓ Passed

**MOT #15** 2021-02-09 11:43**MOT test number** 600103404943**Result** ✓ Passed**MOT #14** 2020-01-09 11:10**MOT test number** 268366232457**Result** ✓ Passed**Advice** Front Exhaust mounting defective Bracket broken, rubber missing (6.1.2 (a))**Advice** Steering column top bearing slightly worn (2.2.2 (b))**MOT #13** 2020-01-07 13:50**MOT test number** 538606587165**Result** ✗ Failed**Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Front Exhaust mounting defective Bracket broken, rubber missing (6.1.2 (a))**Advice** Steering column top bearing slightly worn (2.2.2 (b))**MOT #12** 2019-01-09 10:06**MOT test number** 732677766722**Result** ✓ Passed

**MOT #11** 2019-01-08 15:57**MOT test number** 552705119290**Result** ✗ Failed**Fail** Rear Service brake excessively fluctuating (1.2.1 (e))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))**Fail** Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #10** 2018-01-05 14:00**MOT test number** 846718510941**Result** ✓ Passed**MOT #9** 2017-01-05 09:38**MOT test number** 775200425099**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2017-01-05 09:38**MOT test number** 817517180239**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Offside Front Headlamp aim too high (1.8)**MOT #7** 2016-01-04 14:38**MOT test number** 455817092803**Result** ✓ Passed**Advice** Engine covers and under trays fitted

**MOT #6** 2016-01-04 14:38**MOT test number** 933294491851**Result** ✗ Failed**Advice** Engine covers and under trays fitted**Pass with rectification** Nearside Front Headlamp aim too low (1.8)**MOT #5** 2015-01-02 12:23**MOT test number** 388302405054**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #4** 2015-01-02 12:23**MOT test number** 786402005059**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Pass with rectification** Offside Front Headlamp aim too low (1.8)**Notice** Engine covers fitted obscuring some components in the engine bay**Pass with rectification** Nearside Front Headlamp aim too low (1.8)**MOT #3** 2013-12-20 13:00**MOT test number** 455004453464**Result** ✓ Passed



MOT #2	2012-12-21 14:52
MOT test number	107816552315
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2011-12-16 11:07
MOT test number	906080151310
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
3 January 2025

Tax status	Valid until 1 January
Days left	247
MOT expiry date	3 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	EK58YNB
Plate since	2024-03-28
Current registration	EK58YNB
Plate since	2024-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-12-29
Last registration	2023-12-07
Complete history	See info



Registration #1	2008-12-29	22 mi
Registration #2	2011-12-16	35.362 mi
Registration #3	2012-12-21	44.465 mi
Registration #4	2013-12-20	52.045 mi
Registration #5	2015-01-02	57.577 mi
Registration #6	2016-01-04	59.525 mi
Registration #7	2016-01-04	59.525 mi
Registration #8	2017-01-05	61.623 mi
Registration #9	2017-01-05	61.623 mi
Registration #10	2018-01-05	63.727 mi
Registration #11	2019-01-05	65.831 mi
Registration #12	2019-01-05	65.831 mi
Registration #13	2019-01-05	65.831 mi
Registration #14	2019-01-05	65.831 mi
Registration #15	2019-01-05	65.831 mi
Registration #16	2019-01-05	65.831 mi
Registration #17	2019-01-05	65.831 mi
Registration #18	2019-01-05	65.831 mi
Registration #19	2019-01-05	65.831 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1805 mm
Height	1480 mm
Length	4735 mm
Wheel base	2720 mm
Kerb weight	1408 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	G4KA6H00301