



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN SEL TSI BLUEMOTION TECHNOLOGY DSG
Colour	Grey
Year of manufacture	2018
Top speed	130 mph
0 - 100 km/h	8.9 seconds
0 - 60 mph	11.9 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	110 kW / 150 HP / 148 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.395 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	51.4 mpg
CO2 emission	127 g/km
CO2 label	D





Internet history

Entry 1

Date	2022-07-06
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-25
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	9
Total items failed	5

MOT #5	2023-05-26 12:09
MOT test number	670170957110
Result	✓ Passed
Next expiry date	2024-05-25

MOT #4	2023-05-25 10:05
MOT test number	208322004041

Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Front Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Front Headlamp aim too high (4.1.2 (a))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #3** 2022-01-06 15:46**MOT test number** 143470418839**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #2** 2022-01-06 12:44**MOT test number** 512709143839**Result** ✗ Failed**Advice** Nearside Rear Nail in tyre**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #1** 2021-01-19 11:56**MOT test number** 524670785372**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
25 May 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	25 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 RJ67VUM
Plate since	2019-06-29
Current registration	 RJ67VUM
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-01-17
Last registration	2023-05-26
Complete history	See info



Registration #1	2018-01-17	11 mi
Registration #2	2021-01-19	14.358 mi
Registration #3	2022-01-06	18.573 mi
Registration #4	2022-01-06	18.573 mi
Registration #5	2023-05-26	25.277 mi
Registration #6	2023-05-26	25.277 mi
Registration #7	2023-05-26	25.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	89%
Pedestrian	71%
Safety systems	76%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1829 mm
Height	1628 mm
Length	4527 mm
Wheel base	2791 mm
Kerb weight	1478 kg
Max. allowed weight	2230 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Number of axles	2
Engine number	CZDA861045