






report date: 2024-03-28

General information

Make	TOYOTA
Model	VERSO VALVEMATIC ICON
Colour	Grey
Year of manufacture	2017
Top speed	115 mph
0 - 60 mph	11.1 seconds
Gearbox	7 speed CVT

Engine & fuel consumption

Power	147 BHP
Max. torque	180 Nm at 4.000 rpm
Engine capacity	1.798 сс
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.8 mpg
CO2 emission	153 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Е,	2+	PA.	, 7)

y -	
Date	2021-07-01
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Lifting 1	
Date	2021-07-01
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-11-21
MOT pass rate	56 %
MOT passed	5
Failed MOT tests	4
Total advice items	13
Total items failed	5

MOT #9	2023-11-22 09:55
MOT test number	592292721175
Result	✓ Passed
Next expiry date	2024-11-21

МОТ	#8	2023-11-21 10:10
мот	test number	224146349694
Resu	lt	× Failed
Fai	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Mir	nor Registration plate lamp inoperative in the case of multiple lamps or light sour	ces (4.7.1 (b) (i))
Fai	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3	(h))

MOT #7	2022-11-21 12:52
MOT test number	393773270812
Result	✓ Passed
MOT #6	2022-11-21 09:58
MOT test number	553500950026
Result	X Failed
Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Advice Offside Front day light running light not working	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #5

MOT test number

909939069981

Result

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #4

MOT test number

Result

Pass with rectification

Nearside Headlamp aim too low (4.1.2 (a))

Advice

Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT test number

614889442693

Result

Advice (a) (ii))

Advice Rear Tyre slightly damaged/cracking or perishing both rear tyres (5.2.3 (d) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn (5.2.3 (e))

MOT #2 2020-11-19 10:06 **MOT** test number 777841776161 Result × Failed **Advice** Rear Tyre slightly damaged/cracking or perishing both rear tyres (5.2.3 (d) (ii)) **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both front discs worn (1.1.14 (a) (ii)) Nearside Front Tyre worn close to legal limit/worn on edge worn (5.2.3 (e)) Advice **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Fail Offside Front Outer Tyre has a lump, caused by separation or partial failure of its structure sidewall (marked yellow) (5.2.3 (d) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #1

MOT test number

813277910402

Result

Advice COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check





Expires: 21 November 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	21 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	1
First licence fee (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



GM17DFU report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history	Owner	history	
---------------	-------	---------	--

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	UK NE
Plate since	
Current registration	NIK NIK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2017-06-23
Last registration	2023-11-22
Complete history	See info



Registration #1	2017-06-23	7 mi
Registration #2	2020-11-19	28.166 mi
Registration #3	2020-11-19	28.166 mi
Registration #4		71.777 66
Registration #5		11.777 es
Registration #6	2021-11-22	31.449 mi
Registration #7		11.777 es
Registration #8		11.777 ea
Registration #9		9.777 es
Registration #10		71.777 66
Registration #11		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
50567	
S0569	

Safety ratings

NCAP rating	****
Adult	89%
Children	75%
Pedestrian	69%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1790 mm
Height	1620 mm
Length	4460 mm
Wheel base	2780 mm
Kerb weight	1540 kg
Max. allowed weight	2125 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/12