





General information

Make	MINI
Model	COUNTRYMAN COOPER SD COOPER SD
Colour	Red
Year of manufacture	2012
Top speed	123 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	65.7 mpg
Consumption combined	61.4 mpg
CO2 emission	122 g/km
CO2 label	D







Internet history

Entry 1

Date Pictures 2021-12-10

Listing price

View report

6









source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-07
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	12
Total items failed	2

MOT #11	2023-10-02 11:59
MOT test number	754617437613
Result	🗸 Passed
Next expiry date 2024-10-	
Advice Surface corrosion front, rear subframes, suspension, shockers, springs	

MOT #10		2022-10-07 10:28
MOT test	number	437656640212
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Surface corrosion front, rear subframes, suspension, rear shockers, springs	

MOT #9	2022-10-06 13:29
MOT test number	308987911758
Result	🗙 Failed
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Surface corrosion front, rear subframes, suspension, rear shockers, springs	





MOT #8	2	021-10-08 12:25
MOT test	number	850576277313
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #7		2020-07-10 14:26
MOT test	number	939174974911
Result		🗸 Passed
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	

МОТ #6	2019-07-06 08:22
MOT test number	254612328203
Result	✓ Passed
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))

MOT #5	2018-07-09 07:55
MOT test number	483145829910
Result	✓ Passed

МОТ #4		2018-07-09 07:55
MOT test number		910870391116
Result		🗙 Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a))	





MOT #3	2017-07-12 10:12
MOT test number	776591458101
Result	✓ Passed
Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
MOT #2	2016-07-20 07:55
MOT test number	515057698365
Result	✓ Passed
MOT #1	2015-07-22 15:37
MOT test number	729533505234
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 December 2024	✓ MOT Expires: 7 October 2024
Tax status	Valid until 1 December
Days left	216
MOT expiry date	7 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-





Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-06-28
Last registration	2023-10-02
Complete history	<u>See info</u>



Registration #1	2012-06-28	26 mi
Registration #2	2015-07-22	20.332 mi
Registration #3	2016-07-20	30.157 mi
Registration #4	2017-07-12	37.933 mi
Registration #5	2018-07-09	44.202 mi
Registration #6	2018-07-09	44.202 mi
Registration #7	2019-07-06	5.057 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 est
Registration #13		11.777 esi

More info >





Car features

S0225	Air conditioning
\$0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight	
Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2595 mm
Kerb weight	1320 kg
Max. allowed weight	1830 kg
Additional information	
Fuel tank capacity	47
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12