





General information

Make	BMW
Model	430 430D XDRIVE M SPORT
Colour	Blue
Year of manufacture	2015
Top speed	155 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	255 BHP
Max. torque	560 Nm at 1.500 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	57.7 mpg
Consumption combined	52.3 mpg
CO2 emission	142 g/km
CO2 label	F






Internet history

Entry 4	
Date	2023-08-12
Pictures	10
Listing price	View report



source: autoonline.co.uk

Entry 3		
Date	2023-08-06	
Pictures	10	
Listing price	View report	




source: autoonline.co.uk

Entry 2	
Date	2023-07-12
Pictures	0
Listing price	View report

source: carcraft.co.uk

Entry 1	
Date	2021-01-28
Pictures	10
Listing price	View report









source: autoonline.co.uk



MOT history

MOT expiry date	2024-08-08
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	12
Total items failed	1

MOT #7	2023-08-09 10:45
MOT test number	861631855528
Result	✓ Passed
Next expiry date	2024-08-08

МОТ #6	2022-07-16 11:44
MOT test number	271434233256
Result	✓ Passed

MOT #5	2021-07-07 14:32
MOT test number	862825349672
Result	✓ Passed
Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	





MOT #4		2020-07-16 08:27
MOT test	number	373551863191
Result		✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge bald on inner edge (5.2	2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge bald on inner edge (5	5.2.3 (e))
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2	2.3 (d) (i))
Advice	Offside Rear Nail in tyre	

MOT #3 2020-07-16 08:27 987649679922 **MOT test number** Result × Failed Advice Offside Rear Tyre worn close to legal limit/worn on edge bald on inner edge (5.2.3 (e)) Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) Advice Offside Rear Nail in tyre Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) Nearside Rear Tyre worn close to legal limit/worn on edge bald on inner edge (5.2.3 (e)) Advice Pass with rectification Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #2	2019-07-18 13:51
MOT test number	236867055347
Result	✓ Passed

MOI #1		2018-03-29 08:45
MOT test	number	588892562344
Result		✓ Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A'	stone chip (8.3.1d)



Tax & MOT check

✓ Taxed	√ МОТ
1 November 2024	Expires: 8 August 2024
Tax status	Valid until 1 November
Days left	187
MOT expiry date	8 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Date	A.F.
Category	ante.
Туре	

Extra BMW salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this BMW had different number plate	es.
Number of plates	
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-04-10
Last registration	2023-08-09
Complete history	See info



Registration #1	2015-04-10	29 mi
Registration #2	2018-03-29	40.622 mi
Registration #3	2019-07-18	51.239 mi
Registration #4	2020-07-16	64.214 mi
Registration #5	2020-07-16	64.214 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.117 mi





Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	95%
Children	84%
Pedestrian	78%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight	
Width	1825 mm
Height	1392 mm
Length	4638 mm
Wheel base	2810 mm
Kerb weight	1615 kg
Max. allowed weight	2135 kg
Additional information	
Fuel tank capacity	57
Fuel delivery	Direct Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 11/11

Number of axles	2
Engine number	76869217