



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	HILUX ACTIVE 4X4 D-4D S/C
Colour	Red
Year of manufacture	2015
Top speed	106 mph
0 - 60 mph	15.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	142 BHP
Max. torque	343 Nm at 2.800 rpm
Engine capacity	2.494 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	42.8 mpg
Consumption combined	38.7 mpg
CO2 emission	193 g/km
CO2 label	J






Internet history

Entry 1

Date	2021-10-24
Pictures	11
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

**MOT history**

<b>MOT expiry date</b>	2024-10-08
<b>MOT pass rate</b>	75 %
<b>MOT passed</b>	6
<b>Failed MOT tests</b>	2
<b>Total advice items</b>	13
<b>Total items failed</b>	11

<b>MOT #8</b>	2023-10-09 14:26
<b>MOT test number</b>	215166595619
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-10-08

<b>MOT #7</b>	2022-10-07 09:53
<b>MOT test number</b>	192989830894
<b>Result</b>	✓ Passed

<b>MOT #6</b>	2021-10-06 11:54
<b>MOT test number</b>	918583652973
<b>Result</b>	✓ Passed

**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**Advice** Offside Play in steering rack inner joint(s) Slight



MOT #5

2021-09-20 15:34

MOT test number

451570926698

Result

✗ Failed

- Fail

Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
- Advice

Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice

Play in steering rack inner joint(s) Both slight play
- Fail

Trailer electrical socket (13 pin) not operating the trailer lamps as intended (4.10 (c) (i))
- Fail

Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
- Minor

Nearside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice

Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail

Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #4**

2021-08-31 16:57

**MOT test number**

875373128442

**Result**

✗ Failed

**Fail**

Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))

**Fail**

Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

**Advice**

Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**Minor**

Nearside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Advice**Front Vehicle structure is deformed but structural rigidity is not significantly reduced  
Crossmember (6.1.1 (a) (i))**Fail**

Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))

**Fail**

Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))

**Fail**Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords  
(5.2.3 (d) (i))**Fail**

Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

**Advice**

Nearside Play in steering rack inner joint(s)

**Fail**

Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))

**MOT #3**

2020-08-05 11:54

**MOT test number**

665461838711

**Result**

✓ Passed

**Advice**

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #2**

2019-08-20 15:48

**MOT test number**

970203985719

**Result**

✓ Passed

**MOT #1**

2018-09-04 14:20

**MOT test number**

812112782468

**Result**

✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
8 October 2024

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	8 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 275,00,-
<b>Standard rate (6 months)</b>	£ 151,25,-




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-09-04
Last registration	2023-10-09
Complete history	<a href="#">See info</a>



Registration #1	2015-09-04	9 mi
Registration #2	2018-09-04	11.359 mi
Registration #3	2019-08-20	15.161 mi
Registration #4	2020-08-05	18.513 mi
Registration #5	2021-08-31	21.704 mi
Registration #6	2022-05-20	25.277 mi
Registration #7	2022-05-20	25.277 mi
Registration #8	2022-05-20	25.277 mi
Registration #9	2022-05-20	25.277 mi
Registration #10	2023-10-09	25.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1795 mm
Length	5260 mm
Kerb weight	1910 kg
Max. allowed weight	2730 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	2KDA684869