





report date: 2024-03-28

General information

Make	MINI
Model	COUNTRYMAN COOPER SD COOPER SD
Colour	Green
Year of manufacture	2012
Top speed	123 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	65.7 mpg
Consumption combined	61.4 mpg
CO2 emission	122 g/km
CO2 label	D



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2022-01-08

Pictures 17

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2025-01-17
MOT pass rate	100 %
MOT passed	10
Failed MOT tests	0
Total advice items	13
Total items failed	0

MOT #10	2024-01-18 11:52
MOT test number	458082233654
Result	✓ Passed
Next expiry date	2025-01-17

MOT #9	2023-01-03 16:02
MOT test number	171625577261
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Nearside Registration plate lamp inoperative in the case of multiple lamp (b) (i))	os or light sources (4.7.1

MOT #8	2022-01-13 11:23
MOT test number	427793863153
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #7		2020-12-11 09:48
MOT test	number	312381689441
Result		✓ Passed
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))	

MOT #6		2019-12-19 09:49
MOT test	number	442015859415
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	

Advice Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	
MOT #5	2018-12-31 11:55
MOT test number	170843971972
Result	✓ Passed
MOT #4	2018-06-14 07:46
MOT test number	784488758362
Result	✓ Passed
MOT #3	2017-06-13 12:46

MOT #3	2017-06-13 12:46
MOT test number	472662392340
Result	✓ Passed

CarCheck.co.uk page 4/12



MOT #2 2016-06-01 13:04

MOT test number 347673104991

Result ✓ Passed

Advice Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #1 2015-06-18 09:30

MOT test number 337199165136

Result

Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	17 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did Check it in the premium report and see all owner registrations. Download the full report have the current and see all owner registrations.		e?
THE STATE OF THE S		

	More info	>
Plate changes See in this check if this MINI had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-08-02
Last registration	2024-01-18
Complete history	See info



Registration #1	2012-08-02	26 mi
Registration #2	2015-06-18	28.361 mi
Registration #3	2016-06-01	34.521 mi
Registration #4	2017-06-13	41.900 mi
Registration #5	2018-06-14	47.750 mi
Registration #6	2018-12-31	49.012 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2595 mm
Kerb weight	1320 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	47
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12