



RENAULT

 **HW6IKWD**

report date: 2024-03-28

General information

Make	RENAULT
Model	GRAND SCENIC GRAND DYNAMIQUE TOMTOM DCI
Colour	Black
Year of manufacture	2012
Top speed	112 mph
0 - 60 mph	13.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.6 mpg
CO2 emission	128 g/km
CO2 label	D






Internet history

Entry 2

Date	2022-03-27
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)

Entry 1

Date	2021-10-05
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)



MOT history

MOT expiry date	2024-10-27
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	45
Total items failed	10

MOT #13	2023-10-28 10:23
---------	------------------

MOT test number	983757554685
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-10-27
------------------	------------

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn to 3mm (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement D bushes (5.3.4 (a) (i))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #12**

2023-10-26 15:35

**MOT test number**

861196072934

**Result****✗ Failed**

- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn to 3mm (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Rear Service brake imbalanced across an axle (1.2.1 (b) (i))
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement D bushes (5.3.4 (a) (i))

**MOT #11**

2022-10-12 10:20

**MOT test number**

303385213901

**Result****✓ Passed**

- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #10**

2021-10-27 09:07

**MOT test number**

397717788151

**Result****✓ Passed**

**MOT #9**

2021-10-21 16:51

**MOT test number**

394032669080

**Result****✗ Failed**

- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Rear Direction indicator incorrect colour BOTH sides (4.4.3 (a))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Rear Outer Brake pad(s) less than 1.5 mm thick BOTH sides (1.1.13 (a) (ii))

**MOT #8**

2020-09-30 10:00

**MOT test number**

931431122385

**Result****✓ Passed**

- Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear damage to door and 1/4
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #7** 2020-09-30 10:00**MOT test number** 879563266745**Result** ✗ Failed

- Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear damage to door and 1/4
- Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #6** 2019-08-08 10:25**MOT test number** 283982227386**Result** ✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Nail in tyre
- Advice** Nearside Rear damage to door and 1/4 panel
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #5** 2018-08-13 08:40**MOT test number** 148749626021**Result** ✓ Passed

- Advice** Nearside Rear 1/4 and door damaged

**MOT #4** 2017-09-06 10:43**MOT test number** 359007892218**Result** ✓ Passed**Advice** Engine light on**Advice** Passenger airbag turned off**Advice** Central Child Seat fitted not allowing full inspection of adult belt**MOT #3** 2016-08-24 12:12**MOT test number** 744646556801**Result** ✓ Passed**MOT #2** 2015-08-21 08:10**MOT test number** 415655146890**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nail in offside rear tyre**Advice** Undertray fitted**MOT #1** 2014-11-06 10:39**MOT test number** 537010414342**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
27 October 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	217
<b>MOT expiry date</b>	27 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-





Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-01-18
Last registration	2023-10-28
Complete history	<a href="#">See info</a>



Registration #1	2012-01-18	28 mi
Registration #2	2014-11-06	20.473 mi
Registration #3	2015-08-21	28.410 mi
Registration #4	2016-08-24	35.796 mi
Registration #5	2017-09-06	41.068 mi
Registration #6	2018-08-13	44.363 mi
Registration #7	2019-08-08	49.187 mi
Registration #8	2020-09-30	53.834 mi
Registration #9	2021-09-29	55.277 mi
Registration #10	2022-09-29	55.277 mi
Registration #11	2023-09-29	55.277 mi
Registration #12	2024-09-29	55.277 mi
Registration #13	2025-09-29	55.277 mi
Registration #14	2026-09-29	55.277 mi
Registration #15	2027-09-29	55.277 mi
Registration #16	2028-09-29	55.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	76%
Pedestrian	42%
Safety systems	99%
Overall rating	79%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2077 mm
Height	1645 mm
Length	4560 mm
Wheel base	2770 mm
Kerb weight	1430 kg
Max. allowed weight	2128 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number	D265107
---------------	---------