





report date: 2024-03-28

General information

Maka	NUCCAN
Make	NISSAN
Model	NOTE ACENTA
Colour	Blue
Year of manufacture	2015
Top speed	106 mph
0 - 60 mph	13.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	80 BHP
Max. torque	110 Nm at 4.000 rpm
Engine capacity	1.198 сс
Cylinders	3
Fuel type	Petrol
Consumption city	47.9 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2021-07-06

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



VE15PVF

report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2024-07-31
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	6
Total items failed	4

MOT #9	2023-07-28 10:19
MOT test number	678661663928
Result	✓ Passed
Next expiry date	2024-07-31

MOT #8	2023-07-28 07:50
MOT test number	217714915034
Result	× Failed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #7	2022-07-09 09:35
MOT test number	682202218883
Result	✓ Passed

MOT #6	2021-07-20 08:58
MOT test number	744221969026
Result	✓ Passed

MOT #5	2020-07-20 14:40
MOT test number	258270200411
Result	✓ Passed

CarCheck.co.uk page 3/11



VE15PVF

report date: 2024-03-28

MOT #4

MOT test number

Result

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #3 2019-07-25 10:19 **MOT** test number 911768747567 Result × Failed Fail Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) **Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #2

2018-08-01 11:30

MOT test number

208093977719

Result

✓ Passed

MOT #1

2018-08-01 11:30

MOT test number

513036824349

Result

✓ Failed

Pass with rectification

Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	31 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

Owner History	
For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	NIE
Plate since	
Current registration	NK SIX
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-05-28
Last registration	2023-07-28
Complete history	See info



Registration #1	2015-05-28	26 mi
Registration #2	2018-08-01	31.801 mi
Registration #3	2018-08-01	31.801 mi
Registration #4	2019-07-25	40.267 mi
Registration #5	2019-08-01	40.398 mi
Registration #6	2020-07-20	47.555 mi
Registration #7		11.777 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		0.074
Registration #11		10.777 au

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	86%
Children	82%
Pedestrian	58%
Safety systems	70%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1530 mm
Length	4100 mm
Wheel base	2600 mm
Kerb weight	1040 kg
Max. allowed weight	1510 kg

Additional information

Fuel tank capacity	41
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles 2

Engine number 094515R