



report date: 2024-03-29

General information

Make	MINI
Model	MINI COOPER S
Colour	Blue
Year of manufacture	2011
Top speed	142 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	48.7 mpg
CO2 emission	136 g/km
CO2 label	E





Internet history

Entry 2

Date	2021-12-14
Pictures	7
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

Entry 1

Date	2021-02-02
Pictures	1
Listing price	<a href="#">View report</a>



source: autoonline.co.uk



## MOT history

MOT expiry date	2024-06-14
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	27
Total items failed	8

MOT #15	2023-06-08 10:31
MOT test number	553426204018
Result	✓ Passed
Next expiry date	2024-06-14
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2022-06-10 11:30
MOT test number	743671531900
Result	✓ Passed
Advice	Nearside Front Nail in tyre

MOT #13	2022-06-10 11:30
MOT test number	278622357738
Result	✗ Failed
Pass with rectification	Nearside Front Headlamp aim too low (4.1.2 (a))
Advice	Nearside Front Nail in tyre

**MOT #12**

2021-06-15 15:37

**MOT test number**

718644817668

**Result**

✓ Passed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside front brake backplate corroded

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #11**

2021-06-09 09:40

**MOT test number**

945323953131

**Result**

✗ Failed

**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

**Advice** Nearside front brake backplate corroded

**Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #10**

2020-08-12 14:54

**MOT test number**

741211469041

**Result**

✓ Passed

**MOT #9**

2020-02-18 10:41

**MOT test number**

120020524972

**Result**

✓ Passed

**Advice** Nearside Front Inner wheel rim slightly damaged .

**MOT #8** 2019-02-26 11:39**MOT test number** 910485202812**Result** ✓ Passed**MOT #7** 2018-02-27 12:28**MOT test number** 152089881170**Result** ✓ Passed**MOT #6** 2018-02-27 12:28**MOT test number** 865488173774**Result** ✗ Failed**Pass with rectification** Offside Rear Obligatory mirror insecure (8.1.1)**MOT #5** 2017-02-23 12:25**MOT test number** 757787584286**Result** ✓ Passed**MOT #4** 2016-04-08 08:03**MOT test number** 518696720152**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #3**

2015-03-23 17:06

**MOT test number**

456412885007

**Result**

✓ Passed

**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

**Notice** Under-trays fitted obscuring some underside components

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)

**Notice** Engine covers fitted obscuring some components in the engine bay

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Road wheel slightly damaged (4.2.A.1a)

**MOT #2**

2015-03-23 13:29

**MOT test number**

209592585014

**Result**

✗ Failed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Notice** Under-trays fitted obscuring some underside components

**Advice** Offside Front Road wheel slightly damaged (4.2.A.1a)

**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

**Fail** Offside Rear Rear wheel bearing has excessive play (2.6.2)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Notice** Engine covers fitted obscuring some components in the engine bay

**Advice** Nearside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)

**MOT #1**

2014-04-11 13:17

**MOT test number**

876911004143

**Result**

✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
14 June 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	14 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-03-19
Last registration	2023-06-08
Complete history	<a href="#">See info</a>



Registration #1	2011-03-19	26 mi
Registration #2	2014-04-11	29.576 mi
Registration #3	2015-03-23	42.837 mi
Registration #4	2015-03-23	42.842 mi
Registration #5	2016-04-08	56.208 mi
Registration #6	2017-02-23	62.939 mi
Registration #7	2018-02-27	69.527 mi
Registration #8	2018-02-27	69.527 mi
Registration #9	2019-02-26	75.740 mi
Registration #10	2019-03-20	75.777 mi
Registration #11	2019-03-20	75.777 mi
Registration #12	2019-03-20	75.777 mi
Registration #13	2019-03-20	75.777 mi
Registration #14	2019-03-20	75.777 mi
Registration #15	2019-03-20	75.777 mi
Registration #16	2019-03-20	75.777 mi
Registration #17	2019-03-20	75.777 mi
Registration #18	2019-03-20	75.777 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3714 mm
Wheel base	2467 mm
Kerb weight	1130 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	B398J081