




report date: 2024-03-28

General information

Make	FIAT
Model	DOBLO 16V MULTIJET
Colour	White
Year of manufacture	2013
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	133 g/km
CO2 label	E





Internet history

Entry 3


Date	2022-12-15
Pictures	8
Listing price	View report



source: [cargurus.co.uk](#)

Entry 2


Date	2021-12-03
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-07-16
Pictures	1
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-12-13
MOT pass rate	53 %
MOT passed	8
Failed MOT tests	7
Total advice items	31
Total items failed	6

MOT #15	2023-12-07 16:08
MOT test number	390668198374
Result	✓ Passed
Next expiry date	2024-12-13
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #14	2023-12-07 16:08
MOT test number	846162460823
Result	✗ Failed
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Pass with rectification	Front Windscreen washer provides insufficient washer liquid both sides (3.5 (a))

MOT #13	2022-12-14 14:23
MOT test number	863791630096
Result	✓ Passed

**MOT #12** 2022-11-28 14:41**MOT test number** 292260317990**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Pass with rectification** Nearside Front Headlamp aim projected beam image is obviously incorrect Bulb not fitted correctly (4.1.2 (c))**MOT #11** 2022-01-14 15:07**MOT test number** 960751135564**Result** ✓ Passed**MOT #10** 2022-01-14 13:37**MOT test number** 832794713747**Result** ✗ Failed**MAJOR** Rear Brakes imbalanced across an axle (1.2.1 (b) (i))**MAJOR** Exhaust on a vehicle fitted with a diesel particulate filter emits visible smoke of any colour (8.2.2.2 (d))**MAJOR** Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))**MOT #9** 2021-01-27 11:45**MOT test number** 836742336884**Result** ✓ Passed**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

**MOT #8** 2021-01-27 09:35**MOT test number** 552103556714**Result** ✗ Failed

- Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- MAJOR** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #7 2019-07-11 15:44**MOT test number** 627070752200**Result** ✓ Passed

- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Items removed from driver's view prior to test

MOT #6 2019-07-10 08:30**MOT test number** 517011388491**Result** ✗ Failed

- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- MAJOR** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Advice** Items removed from driver's view prior to test
- MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #5** 2018-07-26 10:51**MOT test number** 531134721144**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2017-07-29 12:14**MOT test number** 655459530808**Result** ✓ Passed**MOT #3** 2017-07-29 08:18**MOT test number** 995940888280**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Front brake discs heavily lipped**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside macpherson strut top bearing rough**MOT #2** 2016-07-29 13:34**MOT test number** 528787365968**Result** ✓ Passed**Advice** Clutch pedal anti slip missing**Advice** Engine and under body covers



MOT #12016-07-29 13:34

MOT test number636294674540

Result

Failed

Pass with rectification

Nearside Headlamp aim too low (1.8)

Advice

Clutch pedal anti slip missing

Advice

Engine and under body covers

Pass with rectification

Offside Headlamp aim too low (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
13 December 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	13 December 2024
Full MOT history	See MOT history

Tax calculation


Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	WV63ARX
Plate since	2019-09-28
Current registration	WV63ARX
Plate since	2019-09-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2013-09-05
Last registration	2023-12-07
Complete history	See info



Registration #1	2013-09-05	11 mi
Registration #2	2016-07-29	45.514 mi
Registration #3	2016-07-29	45.514 mi
Registration #4	2017-07-29	50.996 mi
Registration #5	2017-07-29	50.996 mi
Registration #6	2018-07-26	57.861 mi
Registration #7	2019-07-10	63.179 mi
Registration #8	2019-07-11	63.213 mi
Registration #9	2021-01-27	69.636 mi
Registration #10	2021-01-27	69.644 mi
Registration #11	2022-01-27	75.277 mi
Registration #12	2022-01-27	75.277 mi
Registration #13	2022-01-27	75.277 mi
Registration #14	2022-01-27	75.277 mi
Registration #15	2022-01-27	75.277 mi
Registration #16	2022-01-27	75.277 mi
Registration #17	2022-01-27	75.277 mi
Registration #18	2022-01-27	75.277 mi
Registration #19	2022-01-27	75.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	4945767