



OE02AAJ

report date: 2024-03-29

General information

Make	JAGUAR
Model	S-TYPE V6 SE
Colour	Blue
Year of manufacture	2002
Top speed	140 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	201 BHP
Max. torque	249 Nm at 4.000 rpm
Engine capacity	2.496 cc
Cylinders	6
Fuel type	Petrol
Consumption city	19.3 mpg
Consumption extra urban	35.8 mpg
Consumption combined	27.4 mpg
CO2 emission	249 g/km
CO2 label	L






Internet history

Entry 2

Date	2021-12-17
Pictures	6
Listing price	View report



source: autotrader.co.uk

Entry 1

Date	2021-10-14
Pictures	10
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-21
MOT pass rate	68 %
MOT passed	17
Failed MOT tests	8
Total advice items	87
Total items failed	8

MOT #252023-06-22 13:58

MOT test number990036989238

Result✓ Passed

Next expiry date2024-06-21

- Advice

Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive floor pan and inner sill (5.3.6 (a) (i))
- Advice

Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor

Nearside Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice

Offside Rear Suspension component mounting repair covered in underseal (5.3.6 (a) (i))
- Advice

Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive chassis and inner sill (5.3.6 (a) (i))
- Advice

Offside Front Suspension component mounting prescribed area is corroded but not considered excessive inner sill and floor pan (5.3.6 (a) (i))
- Advice

Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice

Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor

Offside Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice

Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive chassis and inner sill (5.3.6 (a) (i))

**MOT #24**

2023-05-11 08:00

MOT test number

305789298771

Result**✗ Failed**

MAJOR Offside Rear Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength chassis holed and corroded around sub frame mounting point (5.3.6 (a) (i))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

DANGEROUS Nearside Rear Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))

MAJOR Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Advice Offside Rear Tyre worn close to legal limit/worn on edge at tread wear indicators (5.2.3 (e))

MOT #23

2022-02-28 09:05

MOT test number

242674319620

Result**✓ Passed**

Advice Both sides inner + outer sills body kit fitted

Minor Nearside Obligatory mirror slightly damaged (3.3 (b) (i))

Minor Offside Obligatory mirror slightly damaged (3.3 (b) (i))

**MOT #22**

2022-02-15 12:59

MOT test number

144156734230

Result**✗ Failed****MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))**MAJOR** Offside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength floor (5.3.6 (a) (i))**MAJOR** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength chassis leg (5.3.6 (a) (i))**Advice** Both sides inner + outer sills body kit fitted**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**MAJOR** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner wheel arch (5.3.6 (a) (i))**MAJOR** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner wheel arch (5.3.6 (a) (i))**MOT #21**

2021-02-16 15:16

MOT test number

506365068584

Result**✓ Passed****Advice** Both headlamps outer lenses faded**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Front Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Nearside Rear Outer Nail in tyre

**MOT #20**

2020-03-17 11:56

MOT test number

966317926243

Result

✓ Passed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Offside Rear Suspension rod ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Rear Lower Suspension rod pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Lower Suspension rod pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Central Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear upper and lower suspension arms bushes boots split
- Minor** Nearside Rear Suspension rod ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Lower Suspension rod pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Brake pipe corroded, covered in grease or other material brake pipe front to back corrosion (1.1.11 (c))
- Advice** Plastic under-trays covering floor pan and sills both sides
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #19

2019-01-25 12:04

MOT test number

160462109511

Result

✓ Passed

**MOT #18** 2018-06-04 10:57**MOT test number** 861694862655**Result** ✓ Passed**Advice** Offside Rear Lower Suspension component pin or bush slightly worn shock bush (5.3.4 (a) (i))**MOT #17** 2018-05-30 10:23**MOT test number** 632432883575**Result** ✗ Failed**MAJOR** Offside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Nearside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))**Advice** Offside Rear Lower Suspension component pin or bush slightly worn shock bush (5.3.4 (a) (i))**Advice** Nearside Front Lower drop link, half of bush missing.**MOT #16** 2017-06-07 12:52**MOT test number** 621397313241**Result** ✓ Passed**Advice** Various brake pipes greased.**Advice** Offside Front tyre, wearing/worn on inside edge**MOT #15** 2017-06-06 10:06**MOT test number** 292078589253**Result** ✗ Failed**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Various brake pipes greased.**Advice** Offside Front tyre, wearing/worn on inside edge



MOT #14	2016-06-18 09:04
----------------	------------------

MOT test number	972899049825
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #13	2015-06-25 11:10
----------------	------------------

MOT test number	189586275115
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #12	2014-08-05 16:57
----------------	------------------

MOT test number	885557214249
------------------------	--------------

Result	✓ Passed
---------------	----------

- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front Vehicle structure has slight corrosion (6.1.A.1)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #11**

2013-07-23 16:01

MOT test number

487174703210

Result

✓ Passed

- Advice** Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Advice** Offside Body has slight corrosion (6.1.B.2)
- Advice** Offside Rear Vehicle structure has slight corrosion (6.1.A.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)
- Advice** Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Advice** Nearside Body has slight corrosion (6.1.B.2)
- Advice** Nearside Rear Vehicle structure has slight corrosion (6.1.A.1)
- Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Nearside Rear Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)

MOT #10

2012-07-09 09:33

MOT test number

525061792155

Result

✓ Passed

- Advice** Nearside Front Tie bar/rod ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

MOT #9

2012-06-28 10:08

MOT test number

269050582476

Result

✗ Failed

- Fail** Offside Rear Upper Tie bar/rod ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)
- Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Nearside Front Tie bar/rod ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**MOT #8** 2011-07-11 12:53**MOT test number** 845422491115**Result** ✓ Passed

- Notice** Oil leak
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Notice** Both rear handbrake cables outer cover worn
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #7 2010-08-06 16:29**MOT test number** 791618410205**Result** ✓ Passed**MOT #6** 2010-08-06 10:02**MOT test number** 103808910246**Result** ✗ Failed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Both parking brake cables rubbing on suspension

MOT #5 2009-07-28 17:15**MOT test number** 871129209207**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #4	2009-07-27 12:27
MOT test number	344968709457
Result	✗ Failed
Fail	Rear parking brake recording little or no effort (3.7.B.6a)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Parking brake: efficiency below requirements (3.7.B.7)

MOT #3	2008-07-17 09:57
MOT test number	163189498179
Result	✓ Passed

MOT #2	2007-08-03 12:06
MOT test number	810165417243
Result	✓ Passed

MOT #1	2007-08-03 12:06
MOT test number	411035417279
Result	✗ Failed
Pass with rectification	Offside Registration plate lamp not working (1.1.5c)
Pass with rectification	Offside Headlamp not working on dipped beam (1.7.5a)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
21 June 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	21 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2002-07-17
Last registration	2023-06-22
Complete history	See info



Registration #1	2002-07-17	25 mi
Registration #2	2007-08-03	48.636 mi
Registration #3	2008-07-17	52.067 mi
Registration #4	2009-07-27	55.519 mi
Registration #5	2009-07-28	55.519 mi
Registration #6	2010-08-06	61.523 mi
Registration #7	2010-08-06	61.535 mi
Registration #8	2011-07-11	65.613 mi
Registration #9	2012-06-28	67.026 mi
Registration #10	2012-07-09	67.036 mi
Registration #11	2013-07-23	68.940 mi
Registration #12	2014-08-05	70.382 mi
Registration #13	2015-06-25	72.476 mi
Registration #14	2016-06-18	75.589 mi
Registration #15	2016-06-18	75.589 mi
Registration #16	2016-06-18	75.589 mi
Registration #17	2016-06-18	75.589 mi
Registration #18	2016-06-18	75.589 mi
Registration #19	2016-06-18	75.589 mi
Registration #20	2016-06-18	75.589 mi
Registration #21	2016-06-18	75.589 mi
Registration #22	2016-06-18	75.589 mi
Registration #23	2016-06-18	75.589 mi
Registration #24	2016-06-18	75.589 mi
Registration #25	2016-06-18	75.589 mi
Registration #26	2016-06-18	75.589 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2040 mm
Height	1444 mm
Length	4861 mm
Wheel base	2909 mm
Kerb weight	1663 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	69 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	281552376JB