



Mercedes-Benz



report date: 2024-03-29

General information

|                     |                   |
|---------------------|-------------------|
| Make                | MERCEDES          |
| Model               | GL GL420 CDI      |
| Colour              | Black             |
| Year of manufacture | 2006              |
| Top speed           | 143 mph           |
| 0 - 60 mph          | 7.6 seconds       |
| Gearbox             | 7 speed automatic |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 302 BHP             |
| Max. torque             | 700 Nm at 2.200 rpm |
| Engine capacity         | 3.996 cc            |
| Cylinders               | 8                   |
| Fuel type               | Diesel              |
| Consumption city        | 18.1 mpg            |
| Consumption extra urban | 30.7 mpg            |
| Consumption combined    | 24.4 mpg            |
| CO2 emission            | 313 g/km            |
| CO2 label               | M                   |







Internet history

Entry 2

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-06-13                  |
| Pictures      | 22                          |
| Listing price | <a href="#">View report</a> |



source: [yesauto.com](#)

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-02-02                  |
| Pictures      | 1                           |
| Listing price | <a href="#">View report</a> |



source: [autoonline.co.uk](#)

**MOT history**

|                           |            |
|---------------------------|------------|
| <b>MOT expiry date</b>    | 2022-03-03 |
| <b>MOT pass rate</b>      | 67 %       |
| <b>MOT passed</b>         | 10         |
| <b>Failed MOT tests</b>   | 5          |
| <b>Total advice items</b> | 71         |
| <b>Total items failed</b> | 14         |

**MOT #15** 2021-03-04 10:00**MOT test number** 333575896777**Result** ✓ Passed**Next expiry date** 2022-03-03**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #14** 2021-02-23 11:14**MOT test number** 101034093759**Result** ✗ Failed**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Road wheel fixing missing (5.2.1 (a) (i))**Fail** Offside Rear Brake pipe excessively corroded front to rear (1.1.11 (c))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Rear Brake pipe excessively corroded front to rear (1.1.11 (c))



MOT #13

2018-09-05 15:02

MOT test number

790426209207

Result

✓ Passed

- Advice

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Offside Brake pipe corroded, covered in grease or other material Front to rear corroding at rear (1.1.11 (c))
- Advice

Offside Front Brake pipe corroded, covered in grease or other material Corroding At hose union (1.1.11 (c))
- Advice

Offside Brake pipe corroded, covered in grease or other material Front to rear corroding at rear (1.1.11 (c))
- Minor

Nearside Front Upper Windscreen damaged but not adversely affecting driver's view Crack at top of screen (3.2 (a) (i))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge Low and worn edges (5.2.3 (e))
- Advice

Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice

Brake pedal wearing smooth (1.1.2 (c))
- Minor

Windscreen damaged but not adversely affecting driver's view Central (3.2 (a) (i))
- Advice

Central Oil leak, but not excessive Leaking but not in excess of requirement - THIS NEEDS FIXING AS OIL ALL OVER UNDERSIDE OF CAR AND EXHAUST - CHILD SEATS IN CAR ENVIRONMENTAL AND SAFETY. (8.4.1 (a) (i))

**MOT #12**

2018-08-31 14:08

**MOT test number**

543812885233

**Result****✗ Failed****Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Offside Rear Stop / tail 1/2 working**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Brake performance not tested Due to leak and tyre (needs use of decelerometer on road to test) (1.2.1 (g))**Minor** Windscreen damaged but not adversely affecting driver's view Central (3.2 (a) (i))**Advice** Brake pedal wearing smooth (1.1.2 (c))**Advice** Offside Brake pipe corroded, covered in grease or other material Front to rear corroding at rear (1.1.11 (c))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Low and worn edges (5.2.3 (e))**Fail** Oil leaking excessively from engine (8.4.1 (a) (i))**Advice** Offside Front Brake pipe corroded, covered in grease or other material Corroding At hose union (1.1.11 (c))**Advice** Offside Brake pipe corroded, covered in grease or other material Front to rear corroding at rear (1.1.11 (c))

**MOT #11**

2017-07-07 11:44

**MOT test number**

155222181364

**Result**

✓ Passed

- Advice** Nearside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Brake pedal rubber worn
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Offside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Crack at top of windscreen
- Advice** Rear Brake pipe slightly corroded n/s and o/s (3.6.B.2c)

**MOT #10**

2017-06-28 13:56

**MOT test number**

983853895543

**Result**

✗ Failed

- Advice** Rear Brake pipe slightly corroded n/s and o/s (3.6.B.2c)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Brake pedal rubber worn
- Advice** Nearside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Fail** Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Crack at top of windscreen
- Fail** Offside front brake binding (3.7.B.1)
- Advice** Offside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)



|                        |  |
|------------------------|--|
| <b>MOT #9</b>          | 2016-07-16 08:57   |
| <b>MOT test number</b> | 115564487759   |
| <b>Result</b>          | ✓ Passed   |
| <b>Advice</b>          | Child Seat fitted not allowing full inspection of adult belt |
| <b>Advice</b>          | Offside sill corroded  |

|                        |  |
|------------------------|--|
| <b>MOT #8</b>          | 2016-07-16 08:10   |
| <b>MOT test number</b> | 415545430261   |
| <b>Result</b>          | ✗ Failed   |
| <b>Fail</b>            | Nearside Front position lamp(s) not working (1.1.A.3b)       |
| <b>Advice</b>          | Child Seat fitted not allowing full inspection of adult belt |
| <b>Fail</b>            | Offside Front position lamp(s) not working (1.1.A.3b)        |
| <b>Advice</b>          | Offside sill corroded  |

|                        |   |
|------------------------|---|
| <b>MOT #7</b>          | 2014-11-07 08:27  |
| <b>MOT test number</b> | 127131214370  |
| <b>Result</b>          | ✓ Passed  |
| <b>Advice</b>          | Rear Brake pad(s) wearing thin (3.5.1g)   |
| <b>Advice</b>          | Offside Front Brake hose slightly deteriorated (3.6.B.4d)   |
| <b>Notice</b>          | Offside park brake cable damaged  |
| <b>Advice</b>          | Offside Rear Brake pipe slightly corroded (3.6.B.2c)  |
| <b>Advice</b>          | Offside Outer Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)  |
| <b>Advice</b>          | Front Brake pad(s) wearing thin (3.5.1g)  |
| <b>Advice</b>          | Nearside Front Brake hose slightly deteriorated (3.6.B.4d)  |
| <b>Advice</b>          | Nearside Rear Brake pipe slightly corroded (3.6.B.2c)   |
| <b>Advice</b>          | Nearside Outer Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a) |

**MOT #6** 2014-11-06 17:05**MOT test number** 697180614323**Result** ✗ Failed**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Fail** Front registration plate missing (6.3.1a)**Advice** Offside Outer Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Outer Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Fail** Nearside Body has a sharp edge caused by damage (6.1.C.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)**Notice** Offside park brake cable damaged**MOT #5** 2013-12-16 15:08**MOT test number** 595830853352**Result** ✓ Passed**MOT #4** 2012-10-12 16:45**MOT test number** 547946682265**Result** ✓ Passed**Advice** Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)



**MOT #3** 2011-11-03 15:48**MOT test number** 439287801338**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #2** 2010-10-29 12:34**MOT test number** 692422500332**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #1** 2009-11-02 12:19**MOT test number** 543496309399**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
21 September 2018

X

MOT

Expired:  
3 March 2022

|                  |                                 |
|------------------|---------------------------------|
| Tax status       | Expired at 21 September         |
| Days left        | 2047 days too late              |
| MOT expiry date  | 3 March 2022                    |
| Full MOT history | <a href="#">See MOT history</a> |

Tax calculation

|   |            |
|---|------------|
| Vehicle class                           | 49         |
| Band                                    | M          |
| Single payment (12 months)              | £ 695,00,- |
| Single six month payment                | £ 382,25,- |
| Total payable by 12 monthly instalments | £ 729,75,- |



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,299 |
| Auction value               | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

|                      |   |
|----------------------|---|
| Number of plates     | 1   |
| Current registration |  SV56DJX |
| Plate since          | 2024-03-29  |
| Current registration |  SV56DJX |
| Plate since          | 2024-03-29  |

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

|                   |            |        |
|-------------------|------------|--------|
| Finance company   | XXXXXXXXXX | XXXXXX |
| Date of agreement | XXXXXXXXXX | XXXXXX |
| Agreement type    | XXXXXXXXXX | XXXXXX |
| Agreement term    | XXXXXXXXXX | XXXXXX |
| Agreement number  | XXXXXXXXXX | XXXXXX |
| Contact info      | XXXXXXXXXX | XXXXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 18                       |
| First mileage registration | 2006-11-01               |
| Last registration          | 2021-03-04               |
| Complete history           | <a href="#">See info</a> |



|                  |            |            |
|------------------|------------|------------|
| Registration #1  | 2006-11-01 | 12 mi      |
| Registration #2  | 2009-11-02 | 42.096 mi  |
| Registration #3  | 2010-10-29 | 54.432 mi  |
| Registration #4  | 2011-11-03 | 70.114 mi  |
| Registration #5  | 2012-10-12 | 84.266 mi  |
| Registration #6  | 2013-12-16 | 102.043 mi |
| Registration #7  | 2014-11-06 | 107.427 mi |
| Registration #8  | 2014-11-07 | 107.427 mi |
| Registration #9  | 2016-07-16 | 118.456 mi |
| Registration #10 | 2016-07-16 | 118.456 mi |
| Registration #11 | 2016-07-16 | 118.456 mi |
| Registration #12 | 2016-07-16 | 118.456 mi |
| Registration #13 | 2016-07-16 | 118.456 mi |
| Registration #14 | 2016-07-16 | 118.456 mi |
| Registration #15 | 2016-07-16 | 118.456 mi |
| Registration #16 | 2016-07-16 | 118.456 mi |
| Registration #17 | 2016-07-16 | 118.456 mi |
| Registration #18 | 2016-07-16 | 118.456 mi |

More info >



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 2127 mm |
| Height              | 1920 mm |
| Length              | 5088 mm |
| Max. allowed weight | 3250 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 100 l            |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 7                |
| Number of axles    | 2                |
| Engine number      | 62991240000982   |