



SD08XFM

report date: 2024-03-28

General information

Make	AUDI
Model	A4 S LINE TDI DPF
Colour	Red
Year of manufacture	2008
Top speed	138 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.986 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G





MOT history

MOT expiry date	2018-05-21
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	50
Total items failed	19

MOT #12 2017-05-19 08:37

MOT test number 475481510326

Result ✓ Passed

Next expiry date 2018-05-21

- Advice** Nearside Rear Nail in tyre
- Advice** Covers fitted in engine bay obscuring view of some components
- Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' three areas of damage - all to an area less than a 10mm circle (8.3.1a)
- Advice** Offside Rear tyre leaking air where valve is seated
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Track rod end ball joint has slight play both sides (2.2.B.1f)
- Advice** Under trays fitted obscuring view of some components
- Advice** Nearside Front Tyre worn close to the legal limit and nail in tyre (4.1.E.1)

MOT #11 2016-05-21 10:38

MOT test number 170164626830

Result ✓ Passed

- Advice** Offside Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)



MOT #10	2016-05-18 16:18
MOT test number	369578522397
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)
Fail	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
Advice	Offside Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

MOT #9	2015-05-22 17:26
MOT test number	598332845199
Result	✓ Passed



MOT #8	2015-05-12 17:01
MOT test number	928802435162
Result	✗ Failed

Fail Offside front brake excessively fluctuating (3.7.B.3)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Front Upper Suspension arm has excessive play in a ball joint (2.4.G.2)

Advice Nearside Rear Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Fail Nearside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)

Advice Centre Rear Seat belt stitching slightly frayed (5.2.2b)

Notice Under-trays fitted obscuring some underside components

Advice Nearside Outer Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

Fail Offside Rear Brake hose excessively deteriorated (3.6.B.4d)

Advice Nearside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Front Shock absorber has a slightly worn bush (2.7.4)

Fail Offside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)

Advice Nearside Rear Brake hose slightly deteriorated (3.6.B.4d)

Fail Offside Rear coil spring broken (2.4.C.1a)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Offside rear brake excessively fluctuating (3.7.B.3)

Advice Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)

Fail Nearside Front Shock absorber has an excessively worn bush (2.7.4)

Advice Offside Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Advice Offside Rear Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Fail Offside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)

Advice Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

Advice Offside Front Shock absorber has a light misting of oil (2.7.3)

Fail Nearside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)

Advice Offside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Fail Nearside Rear coil spring broken (2.4.C.1a)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #7**

2014-03-18 14:29

MOT test number

108197974088

Result

✓ Passed

- Advice** Nearside rear brake fluctuating, but not excessively (3.7.B.3)
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front brake fluctuating, but not excessively (3.7.B.3)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)

MOT #6

2014-03-18 14:29

MOT test number

137107974050

Result

✗ Failed

- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front brake fluctuating, but not excessively (3.7.B.3)
- Pass with rectification** Nearside Headlamp aim too low (1.8)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside rear brake fluctuating, but not excessively (3.7.B.3)
- Pass with rectification** Offside Headlamp aim too low (1.8)

**MOT #5** 2013-03-12 09:09**MOT test number** 169881973413**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #4** 2013-03-11 11:58**MOT test number** 135560473048**Result** ✗ Failed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front brake drum worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Fail** Bonnet retaining device excessively deteriorated (8.4.2)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Noise from n/s/f wheel bearing**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front brake drum worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Notice** Under vehicle paneling insecure**MOT #3** 2012-03-14 15:08**MOT test number** 107164672053**Result** ✓ Passed



MOT #2	2012-03-14 15:08
MOT test number	668384072097
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
Pass with rectification	Nearside Headlamp insecure (1.7.3)

MOT #1	2011-03-21 13:46
MOT test number	269620981081
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
31 October 2017

X

MOT

Expired:
21 May 2018

Tax status	Expired at 31 October 2017
Days left	2372 days too late
MOT expiry date	21 May 2018
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2008-03-29
Last registration	2017-05-19
Complete history	See info



Registration #1	2008-03-29	29 mi
Registration #2	2011-03-21	118.735 mi
Registration #3	2012-03-14	159.649 mi
Registration #4	2013-03-11	196.767 mi
Registration #5	2013-03-12	196.767 mi
Registration #6	2014-03-18	228.430 mi
Registration #7	2015-05-20	251.277 mi
Registration #8	2015-05-20	251.277 mi
Registration #9	2015-05-20	251.277 mi
Registration #10	2015-05-20	251.277 mi
Registration #11	2017-05-19	251.277 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1772 mm
Height	1427 mm
Length	4586 mm
Wheel base	2648 mm
Kerb weight	1510 kg
Max. allowed weight	2060 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	BRD 051741