





report date: 2024-03-29

General information

Make	PEUGEOT
Model	3008 ACCESS
Colour	Blue
Year of manufacture	2014
Top speed	115 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.2 mpg
CO2 emission	155 g/km
CO2 label	G



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-05-25

Pictures 13

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-04-29
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	17
Total items failed	1

MOT #8	2023-04-29 08:09
MOT test number	343604430537
Result	✓ Passed
Next expiry date	2024-04-29

MOT #7	2022-04-29 14:31
MOT test number	596170345011
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

MOT #6	2021-04-30 13:16
MOT test number	274446658318
Result	✓ Passed
Advice Undertray fitted	

CarCheck.co.uk page 3/12



MOT #5 2020-07-15 14:50

MOT test number 516228136684

Result \rightarrow Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Under tray fitted

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #4 2020-07-13 15:19

MOT test number 331200645804

Result X Failed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Under tray fitted

Fail Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #3 2019-05-17 16:19

MOT test number 772711378588

Result

Passed

Advice Engine under tray fitted.

MOT #2 2018-05-23 12:24

MOT test number 321828549590

Result \(\sqrt{Passed} \)

Advice Nearside Rear Nail in tyre

Advice Items removed from driver's view prior to test hanging from interior rear view mirror

Advice Engine under tray.

CarCheck.co.uk page 4/12



MOT #1 2017-05-24 09:17

MOT test number 449270597133

Result ✓ Passed

Advice Under tray fitted

Advice Items removed from driver's view prior to test objects hanging from mirror

Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	29 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
manage of the same	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-05-23
Last registration	2023-04-29
Complete history	See info



Registration #1	2014-05-23	11 mi
Registration #2	2017-05-24	55.874 mi
Registration #3	2018-05-23	73.732 mi
Registration #4	2019-05-17	84.321 mi
Registration #5	2020-07-13	88.414 mi
Registration #6		77,777-46
Registration #6 Registration #7		11,777 ea
		11,777 ea 11,777 ea
Registration #7		11,777 ea 11,777 ea 11,777 ea

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	86%
Children	81%
Pedestrian	31%
Safety systems	97%
Overall rating	75%
Video	see crash video



Dimensions & weight

Width	1837 mm
Height	1640 mm
Length	4365 mm
Wheel base	2613 mm
Kerb weight	1399 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 I	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pa	ge 12/12

Number of axles 2

Engine number FHCL1991966