



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN S TDI 105
Colour	Blue
Year of manufacture	2010
Top speed	111 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	155 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-09-13
Pictures	26
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-09-07
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	33
Total items failed	10

MOT #18	2023-09-08 15:36
MOT test number	747669951262
Result	✓ Passed
Next expiry date	2024-09-07

MOT #17	2022-10-31 14:44
MOT test number	951527325294
Result	✓ Passed

MOT #16	2022-10-31 14:25
MOT test number	756254684162
Result	✗ Failed
Fail	Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #15	2021-10-13 10:37
MOT test number	914129884152
Result	✓ Passed

MOT #14	2021-10-13 10:37
MOT test number	202618302938
Result	✗ Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #13**

2020-11-13 13:56

**MOT test number**

394666365802

**Result**

✓ Passed

**Advice** Offside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #12**

2020-11-10 10:58

**MOT test number**

621630848628

**Result**

✗ Failed

**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #11**

2019-11-04 16:54

**MOT test number**

450919861311

**Result**

✓ Passed

**MOT #10**

2019-11-02 13:03

**MOT test number**

751712748837

**Result**

✗ Failed

**Advice** Offside Front Lower Suspension rod pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**Minor** Offside Front Lower Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice** Nearside Front Lower Suspension rod pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

**Minor** Nearside Front Lower Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Fail** Offside Front Lower Suspension rod ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #9**

2019-02-20 12:03

**MOT test number**

537068924460

**Result**

✓ Passed

**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**Advice** Undershields fitted obscuring some underside components

**MOT #8**

2018-03-05 16:06

**MOT test number**

132070484012

**Result**

✓ Passed

**MOT #7**

2018-03-05 16:06

**MOT test number**

101175947858

**Result**

✗ Failed

**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)



<b>MOT #6</b>	2017-02-23 10:04
<b>MOT test number</b>	315034732145
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Child Seat fitted not allowing full inspection of adult belt

<b>MOT #5</b>	2017-02-21 12:40
<b>MOT test number</b>	390918301901
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Rear Tyre has ply or cords exposed (4.1.D.1b)
<b>Advice</b>	Offside Front tyre worn inner edge
<b>Advice</b>	Nearside Rear tyre worn inner edge
<b>Pass with rectification</b>	Nearside Rear position lamp(s) has less than 50% of the light sources illuminating (1.1.A.3b)
<b>Advice</b>	Rear Child Seat fitted not allowing full inspection of adult belt
<b>Advice</b>	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Tyre worn inner edge
<b>Pass with rectification</b>	Nearside Stop lamp not working (1.2.1b)

<b>MOT #4</b>	2016-02-24 11:25
<b>MOT test number</b>	504058973595
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Nearside Rear Tyres has a small cut to outer sidewall
<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #3** 2015-02-18 10:58**MOT test number** 315469345099**Result** ✓ Passed

- Notice** Child seat fitted not allowing full inspection of adult belt
- Notice** Nearside Rear Tyre Wearing Inside Edge
- Notice** Under-trays fitted obscuring some underside components
- Notice** Offside Rear Tyre Wearing Inside Edge

**MOT #2** 2013-11-20 14:21**MOT test number** 408254923302**Result** ✓ Passed

- Notice** Child seat fitted not allowing full inspection of adult belt
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Offside Inner Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Under-trays fitted obscuring some underside components

**MOT #1** 2012-11-28 15:25**MOT test number** 256983632367**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2025

✓  
**MOT**  
**Expires:**  
7 September 2024

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	367
<b>MOT expiry date</b>	7 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	FV59XGO
Plate since	2019-03-29
Current registration	FV59XGO
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-01-18
Last registration	2023-09-08
Complete history	<a href="#">See info</a>



Registration #1	2010-01-18	24 mi
Registration #2	2012-11-28	19.626 mi
Registration #3	2013-11-20	27.264 mi
Registration #4	2015-02-18	37.919 mi
Registration #5	2016-02-24	48.364 mi
Registration #6	2017-02-21	56.294 mi
Registration #7	2017-02-23	56.353 mi
Registration #8	2018-03-05	65.004 mi
Registration #9	2018-03-05	65.004 mi
Registration #10	2019-02-20	73.273 mi
Registration #11	2019-03-20	75.277 mi
Registration #12	2019-03-20	75.277 mi
Registration #13	2019-03-20	75.277 mi
Registration #14	2019-03-20	75.277 mi
Registration #15	2019-03-20	75.277 mi
Registration #16	2019-03-20	75.277 mi
Registration #17	2019-03-20	75.277 mi
Registration #18	2019-03-20	75.277 mi
Registration #19	2019-03-20	75.277 mi
Registration #20	2019-03-20	75.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1539 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Number of axles	2
Engine number	BXE C70765