



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	FOX URBAN FOX
Colour	Blue
Year of manufacture	-
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2022-04-23
Pictures	7
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT #20</b>	2023-04-28 14:54
<b>MOT test number</b>	154256894811
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-05-03
<b>Minor</b>	Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
<b>Advice</b>	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

<b>MOT #19</b>	2023-04-28 10:03
<b>MOT test number</b>	149097469797
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Fail</b>	Parking brake efficiency below requirements (1.4.2 (a) (i))
<b>Minor</b>	Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
<b>Fail</b>	Front Windscreen washer not working both washers not working (3.5 (a))

<b>MOT #18</b>	2022-05-04 14:29
<b>MOT test number</b>	788361414107
<b>Result</b>	✓ Passed
<b>Advice</b>	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
<b>Advice</b>	Suspension coil springs corroded
<b>Advice</b>	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
<b>Advice</b>	Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))

<b>MOT #17</b>	2021-08-31 15:59
<b>MOT test number</b>	450553831459
<b>Result</b>	✓ Passed
<b>Advice</b>	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #16**

2021-08-26 09:08

**MOT test number**

198521770817

**Result**

✗ Failed

**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Fail** Brake lever has insufficient reserve travel hand brake (1.1.2 (a))**Fail** Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #15**

2020-09-04 00:28

**MOT test number**

475343041269

**Result**

✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge 185X60R14 wearing inner edge (5.2.3 (e))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 185X60R14 wearing outer edge (5.2.3 (e))**MOT #14**

2020-02-22 12:05

**MOT test number**

612346202705

**Result**

✓ Passed

**MOT #13**

2020-02-22 12:05

**MOT test number**

140147605789

**Result**

✗ Failed

**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #12**

2019-03-06 15:32

**MOT test number**

403018337414

**Result**

✓ Passed

**MOT #11** 2018-11-03 14:46**MOT test number** 561976882864**Result** ✓ Passed**Advice** Oil residue on the engine**Advice** Corrosion to exhaust**MOT #10** 2018-11-03 10:31**MOT test number** 349749049638**Result** ✗ Failed**Advice** Oil residue on the engine**Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Corrosion to exhaust**MOT #9** 2017-11-16 11:38**MOT test number** 642786836356**Result** ✓ Passed**Advice** Slight play in n/s/f steering**Advice** Oil residue on the engine**Advice** Corrosion to exhaust



MOT #8	2017-11-15 09:25
MOT test number	590092135585
Result	✗ Failed
Advice	Oil residue on the engine
Advice	Slight play in n/s/f steering
Fail	Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)
Advice	Corrosion to exhaust
Advice	Both front wipers are smearing slightly
Advice	N/s/f anti roll bar linkage dust cover perished
Fail	Offside Front Lower Suspension arm has excessive play in a pin/bush (2.4.G.2)
Advice	O/s/r brake is slightly binding
Fail	Nearside Registration plate lamp not working (1.1.C.1d)
Advice	Both handbrake cables are swelling

MOT #7	2016-10-17 08:34
MOT test number	497402831219
Result	✓ Passed
Advice	Front brake pads are low
Advice	Corrosion to exhaust
Advice	Corrosion to exhaust

**MOT #6** 2015-06-27 11:34**MOT test number** 455048575135**Result** ✓ Passed

- Notice** N/s/r tyre perishing
- Notice** Corrosion to exhaust
- Notice** O/s/f lower suspension arm bush splitting
- Notice** Oil residue on the engine
- Notice** N/s/f lower suspension arm rear bush splitting

**MOT #5** 2014-06-23 11:00**MOT test number** 869714174166**Result** ✓ Passed

- Notice** Wheel trims fitted
- Notice** Corrosion to front brake discs
- Notice** Oil residue on the engine
- Notice** Corrosion to exhaust
- Notice** Misfire on the engine

**MOT #4** 2013-06-27 10:21**MOT test number** 575158573165**Result** ✓ Passed

- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



MOT #3	2012-06-27 09:08
MOT test number	315809172101
Result	✓ Passed
Advice	Offside Rear Shock absorber has a light misting of oil (2.7.3)
Notice	Nearside front tyre has a cut in the tread

MOT #2	2011-06-16 09:29
MOT test number	117357661153
Result	✓ Passed

MOT #1	2010-06-18 09:14
MOT test number	581059260190
Result	✓ Passed





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>VA07OMR</b>
Plate since	2024-03-28
Current registration	 <b>VA07OMR</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-06-29
Last registration	2023-04-28
Complete history	<a href="#">See info</a>



Registration #1	2007-06-29	22 mi
Registration #2	2010-06-18	29.323 mi
Registration #3	2011-06-16	33.115 mi
Registration #4	2012-06-27	37.572 mi
Registration #5	2013-06-27	38.267 mi
Registration #6	2014-06-23	39.573 mi
Registration #7	2015-06-27	44.216 mi
Registration #8	2016-10-17	51.206 mi
Registration #9	2017-11-15	57.622 mi
Registration #10	2017-11-16	57.622 mi
Registration #11	2018-11-03	62.828 mi
Registration #12	2019-05-29	65.377 mi
Registration #13	2019-05-29	65.377 mi
Registration #14	2019-05-29	65.377 mi
Registration #15	2019-05-29	65.377 mi
Registration #16	2019-05-29	65.377 mi
Registration #17	2019-05-29	65.377 mi
Registration #18	2019-05-29	65.377 mi
Registration #19	2019-05-29	65.377 mi
Registration #20	2019-05-29	65.377 mi
Registration #21	2019-05-29	65.377 mi
Registration #22	2019-05-29	65.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BMD 313622