



report date: 2024-03-29

General information

Make	NISSAN
Model	NAVARA DCI TEKNA 4X4 SHR DCB
Colour	White
Year of manufacture	2018
Top speed	112 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	190 BHP
Max. torque	450 Nm at 2.000 rpm
Engine capacity	2.298 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.9 mpg
CO2 emission	183 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-08-20
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-12-04
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	5
Total items failed	7

MOT #8	2023-11-16 15:57
MOT test number	384812826523
Result	✓ Passed
Next expiry date	2024-12-04

MOT #7	2022-12-05 11:05
MOT test number	999465465157
Result	✓ Passed

MOT #6	2022-12-05 10:22
MOT test number	542602079751
Result	✗ Failed
<b>Fail</b> Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #5	2021-11-11 11:55
MOT test number	681498156617
Result	✓ Passed

MOT #4	2021-05-20 11:27
MOT test number	226921070137
Result	✓ Passed

**MOT #3** 2021-03-24 16:34**MOT test number** 522069029232**Result** ✓ Passed**MOT #2** 2021-03-23 12:58**MOT test number** 704153329299**Result** ✗ Failed

- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #1** 2021-02-22 14:58**MOT test number** 501891949325**Result** ✗ Failed

- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Both front tyres badly worn on inner/outer edges
- Fail** Nearside Front Brake hose bulging under pressure (1.1.12 (d))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
4 December 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	185
<b>MOT expiry date</b>	4 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 320,00,-
<b>Standard rate (6 months)</b>	£ 176,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	EY18FCO
Plate since	2019-03-29
Current registration	EY18FCO
Plate since	2019-03-29

More info >





Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2018-03-20
Last registration	2023-11-16
Complete history	<a href="#">See info</a>



Registration #1	2018-03-20	17 mi
Registration #2	2021-02-22	27.287 mi
Registration #3	2021-03-23	27.301 mi
Registration #4	2021-03-24	27.301 mi
Registration #5	2021-05-20	27.346 mi
Registration #6	2022-05-20	28.377 mi
Registration #7	2022-05-20	28.377 mi
Registration #8	2022-05-20	28.377 mi
Registration #9	2022-05-20	28.377 mi
Registration #10	2023-11-16	28.377 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	79%
Children	78%
Pedestrian	78%
Safety systems	68%
Overall rating	76%
Video	<a href="#">see crash video</a>



Copyright © 2015 Euro NCAP

Dimensions & weight

Width	1850 mm
Height	1840 mm
Length	5330 mm
Wheel base	3150 mm
Kerb weight	1991 kg
Max. allowed weight	3045 kg

Additional information

Fuel tank capacity	73 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	027524C