



report date: 2024-03-29

General information

Make	VAUXHALL
Model	MOVANO
Colour	Blue
Year of manufacture	2017
Gearbox	6 speed Manual

Engine & fuel consumption

Power	128 BHP
Max. torque	330 Nm
Engine capacity	2.299 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	39.2 mpg
Consumption combined	35.8 mpg
CO2 emission	207 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-12-12
Pictures	23
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-06
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	14
Total items failed	1

MOT #7	2024-01-05 12:11
MOT test number	464306142138
Result	✓ Passed
Next expiry date	2025-01-06

MOT #6	2024-01-05 12:11
MOT test number	254008181515
Result	✗ Failed
Pass with rectification	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #5	2023-01-07 08:39
MOT test number	942749117655
Result	✓ Passed
Advice	Front wiper blades are smearing

**MOT #4** 2023-01-05 11:51**MOT test number** 590453456881**Result** ✗ Failed**MAJOR** Nearside Outline marker lamp not working center (4.2.1 (a) (ii))**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Front wiper blades are smearing**MAJOR** Offside Rear Outline marker lamp not working (4.2.1 (a) (ii))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #3** 2022-01-06 15:30**MOT test number** 277695428468**Result** ✓ Passed**MOT #2** 2021-07-05 11:33**MOT test number** 520912908790**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing start perish and crack (5.2.3 (d) (ii))**Minor** Offside Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing start perish and crack (5.2.3 (d) (ii))**Minor** Nearside Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))



MOT #1	2020-07-13 12:39
MOT test number	227997436292
Result	✓ Passed
Advice	Covers & shields fitted
Advice	Offside marker lamp damaged



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
6 January 2025

Tax status	Valid until 1 January
Days left	247
MOT expiry date	6 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner 1	2015-01-01
Owner 2	2015-01-01
Owner 3	2015-01-01
Owner 4	2015-01-01
Owner 5	2015-01-01
Owner 6	2015-01-01

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	LL17PWU
Plate since	2015-01-01
Current registration	LL17PWU
Plate since	2015-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-08-18
Last registration	2024-01-05
Complete history	See info



Registration #1	2017-08-18	26 mi
Registration #2	2020-07-13	9.387 mi
Registration #3	2021-07-05	88.248 mi
Registration #4		
Registration #5	2022-01-06	88.564 mi
Registration #6		
Registration #7		
Registration #8		
Registration #9		

More info >



Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	90%
Pedestrian	67%
Safety systems	100%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	2470 mm
Height	2500 mm
Length	6198 mm
Kerb weight	1984 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	M9T -C058600 L0B