



HYUNDAI




report date: 2024-03-28

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM SE
Colour	Red
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	194 BHP
Max. torque	422 Nm at 2.500 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-09-10
Pictures	50
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-22
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	12
Total items failed	3

MOT #10	2023-09-08 13:07
MOT test number	244751176087
Result	✓ Passed
Next expiry date	2024-09-22

MOT #9	2023-09-08 10:24
MOT test number	963560647057
Result	✗ Failed
Fail	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

MOT #8	2022-09-16 10:20
MOT test number	690056909145
Result	✓ Passed

MOT #7	2021-09-23 09:13
MOT test number	342358999523
Result	✓ Passed

**MOT #6** 2021-09-22 11:18**MOT test number** 266195941405**Result** ✗ Failed

- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2021-07-27 15:58**MOT test number** 873950511043**Result** ✗ Failed

- Advice** Items removed from driver's view prior to test
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge edge and limmit (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Fail** Prop shaft flexible coupling excessively deteriorated rear (6.1.7 (d) (i))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

MOT #4 2020-07-10 10:19**MOT test number** 196717393703**Result** ✓ Passed

- Advice** Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #3	2019-07-24 15:59
MOT test number	431450515794
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2	2018-07-06 07:59
MOT test number	440874807998
Result	✓ Passed

MOT #1	2017-07-26 15:58
MOT test number	820260359702
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
22 September 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	22 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2023-03-28
Current registration	XXXXXX
Plate since	2023-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-07-26
Last registration	2023-09-08
Complete history	See info



Registration #1	2014-07-26	27 mi
Registration #2	2017-07-26	37.256 mi
Registration #3	2018-07-06	48.761 mi
Registration #4	2019-07-24	63.962 mi
Registration #5	2020-07-10	77.468 mi
Registration #6	2021-07-27	87.505 mi
Registration #7	2022-09-08	95.277 mi
Registration #8	2023-09-08	101.277 mi
Registration #9	2024-03-28	101.277 mi
Registration #10	2024-03-28	101.277 mi
Registration #11	2024-03-28	101.277 mi
Registration #12	2024-03-28	101.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	89%
Pedestrian	71%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1880 mm
Height	1690 mm
Length	4690 mm
Wheel base	2700 mm
Kerb weight	1963 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	D4HBDU923293