



report date: 2024-03-28

General information

Make	VOLVO
Model	S80 D3 SE
Colour	Silver
Year of manufacture	2012
Top speed	130 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	60.1 mpg
Consumption combined	50.4 mpg
CO2 emission	148 g/km
CO2 label	F






Internet history

Entry 2


Date	2021-10-13
Pictures	50
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-08-29
Pictures	5
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

**MOT history**

<b>MOT expiry date</b>	2024-07-12
<b>MOT pass rate</b>	80 %
<b>MOT passed</b>	8
<b>Failed MOT tests</b>	2
<b>Total advice items</b>	15
<b>Total items failed</b>	2

**MOT #10** 2023-07-12 09:26**MOT test number** 905169206174**Result** ✓ Passed**Next expiry date** 2024-07-12

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn on inner edge & tread lift (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge bald on outer edge (5.2.3 (e))

**MOT #9** 2023-07-12 09:26**MOT test number** 975889305930**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge bald on outer edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn on inner edge & tread lift (5.2.3 (e))
- Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))

**MOT #8** 2022-07-12 08:31**MOT test number** 512923754512**Result** ✓ Passed

- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #7** 2021-07-13 10:30**MOT test number** 535109674129**Result** ✓ Passed**MOT #6** 2020-05-05 10:40**MOT test number** 801929798838**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2019-01-11 12:08**MOT test number** 784422388068**Result** ✓ Passed**Minor** Nearside Rear Tyre obviously under inflated (5.2.3 (h) (i))**MOT #4** 2019-01-11 12:08**MOT test number** 326006720309**Result** ✗ Failed**Minor** Nearside Rear Tyre obviously under inflated (5.2.3 (h) (i))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**MOT #3** 2017-10-26 15:27**MOT test number** 555463866066**Result** ✓ Passed



MOT #2	2016-10-17 09:23
MOT test number	340088736757
Result	✓ Passed
Advice	Rear Direction indicators slightly discoloured (1.4.A.2f)
Advice	Offside Front Tyre worn close to the legal limit Tyre devoid of tread inner edge (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit Tyre devoid of tread on both edges (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2015-02-12 12:40
MOT test number	637773345025
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
12 July 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	186
<b>MOT expiry date</b>	12 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-01-31
Last registration	2023-07-12
Complete history	<a href="#">See info</a>



Registration #1	2012-01-31	14 mi
Registration #2	2015-02-12	62.724 mi
Registration #3	2016-10-17	87.495 mi
Registration #4	2017-10-26	98.417 mi
Registration #5	2019-01-11	110.998 mi
Registration #6	2019-01-11	110.998 mi
Registration #7	2020-05-05	122.688 mi
Registration #8	2020-05-05	122.688 mi
Registration #9	2020-05-05	122.688 mi
Registration #10	2020-05-05	122.688 mi
Registration #11	2020-05-05	122.688 mi
Registration #12	2020-05-05	122.688 mi
Registration #13	2020-05-05	122.688 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1861 mm
Height	1493 mm
Length	4851 mm
Wheel base	2835 mm
Kerb weight	1684 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1110727