





report date: 2024-03-28

General information

Make	BMW
Model	5 SERIES 525D M SPORT
Colour	Grey
Year of manufacture	2008
Top speed	146 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	400 Nm at 1.300 rpm
Engine capacity	2.993 cc
Cylinders	6
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	172 g/km
CO2 label	Н



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-01-28

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-04-12
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	8
Total items failed	8

MOT #16	2024-04-05 14:12
MOT test number	716911094165
Result	✓ Passed
Next expiry date	2025-04-12

MOT #15	2023-03-30 13:52
MOT test number	755288691261
Result	✓ Passed

MOT #14	2022-04-02 10:04
MOT test number	984982239462
Result	✓ Passed

MOT #13	2021-04-13 12:35
MOT test number	459196819282
Result	✓ Passed
Advice Offside Rear Tyre slightly damaged/cracking or perishing slightly	ht cracking in tread (5.2.3 (d) (ii))

MOT #12	2019-08-13 09:29
MOT test number	185443083673
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #11 2018-07-20 13:01

MOT test number 657818722549

Result \rightarrow Passed

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #10 2018-07-03 10:24

MOT test number 632529887004

Result X Failed

Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside parking brake efficiency low

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Nearside Parking brake inoperative on one side (1.4.1 (a))

Fail Horn not working (7.7 (a) (ii))

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #9 2017-06-29 11:01

MOT test number 115033420830

Result
✓ Passed

MOT #8 2016-03-30 12:43

MOT test number 343976690957

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #7	2015-03-30 17:15
MOT test number	195229485050

MOT #6 2014-03-07 16:13

MOT test number 669936964015

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #5 2013-03-08 09:59

MOT test number 839467263031

Result ✓ Passed

MOT #4 2012-03-02 11:39

MOT test number 847082962062

Result ✓ Passed

MOT #3 2011-03-11 11:05

MOT test number 607640171057

Result X Failed

Advice Rear Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Headlamp aim too low (1.8)

MOT #2 2011-03-11 11:05

MOT test number 657450171051

Result ✓ Passed

Advice Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/13



AVX80DA

report date: 2024-03-28

MOT #1 2010-06-07 14:55

MOT test number 392998550192

Result ✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	12 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

o met metery	
For how long did the current and previous owner(s) have this BMW? How many owners of Check it in the premium report and see all owner registrations. Download the full report	

THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	NK NY
Plate since	
Correct registration	IIK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-03-21
Last registration	2024-04-05
Complete history	See info



Registration #1	2008-03-21	6 mi
Registration #2	2010-06-07	21.835 mi
Registration #3	2011-03-11	34.014 mi
Registration #4	2012-03-02	51.964 mi
Registration #5	2013-03-08	68.607 mi
Registration #6	2014-03-07	83.819 mi
Registration #7	2015-03-30	92.989 mi
Registration #8	2016-03-30	103.604 mi
Registration #9	2017-06-29	111.231 mi
3		
Registration #10		11.77 m
		11.777 ea 21.777 ea
Registration #10		11.77 ea 11.77 ea 11.77 ea
Registration #10 Registration #11		11.77 es 11.77 es 11.77 es
Registration #10 Registration #11 Registration #12		11.77 es 11.77 es 11.77 es
Registration #10 Registration #11 Registration #12 Registration #13		11.77 es 11.77 es 11.77 es 11.77 es
Registration #10 Registration #11 Registration #12 Registration #13 Registration #14		11.777 ea 11.777 ea 11.777 ea 11.777 ea 11.777 ea

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditionir
S0295	
S0482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1846 mm
Height	1468 mm
Length	4841 mm
Wheel base	2888 mm
Kerb weight	1595 kg
Max. allowed weight	2155 kg

Additional information

Fuel tank capacity	70 l	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 13/13

Number of axles 2

Engine number 24586868