



report date: 2024-03-28

General information

Make	SUZUKI
Model	ALTO SZ
Colour	White
Year of manufacture	2014
Top speed	96 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-01-21
Pictures	6
Listing price	<a href="#">View report</a>



source: yesauto.com



## MOT history

MOT expiry date	2025-01-25
MOT pass rate	100 %
MOT passed	8
Failed MOT tests	0
Total advice items	13
Total items failed	0

MOT #8 2024-01-23 10:31

MOT test number 992302454789

Result ✓ Passed

Next expiry date 2025-01-25

**Advice** Front Brake disc worn, but not excessively both front (1.1.14 (a) (i))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front suspension arm back bush unbonded slightly from arm (5.3.4 (a) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge tyre nearing legal limit currently at 3mm also worn slightly on outer edge (5.2.3 (e))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front suspension arm back bush unbonded slightly from arm (5.3.4 (a) (i))

**Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #7 2023-01-10 09:23

MOT test number 910736434649

Result ✓ Passed

**Minor** Front Windscreen wiper blade defective both front wipers split slightly at ends but still clear windscreen (3.4 (b) (i))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front suspension arm back bush unbonded slightly (5.3.4 (a) (i))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front suspension arm back bush unbonded slightly (5.3.4 (a) (i))

**MOT #6** 2022-01-24 13:49**MOT test number** 415271861331**Result** ✓ Passed**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Front Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**MOT #5** 2021-01-26 16:13**MOT test number** 500359095857**Result** ✓ Passed**MOT #4** 2020-10-27 09:29**MOT test number** 965385193955**Result** ✓ Passed**MOT #3** 2019-12-17 11:02**MOT test number** 613888353151**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2018-12-17 11:10**MOT test number** 948061961192**Result** ✓ Passed**MOT #1** 2017-12-12 16:21**MOT test number** 741610943290**Result** ✓ Passed**Advice** Both rear tyres cracking in tread pattern



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
25 January 2025

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	34
<b>MOT expiry date</b>	25 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	<b>PF64LWU</b>
Plate since	2019-09-29
Current registration	<b>PF64LWU</b>
Plate since	2019-09-29

More info >





Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-12-30
Last registration	2024-01-23
Complete history	<a href="#">See info</a>



Registration #1	2014-12-30	14 mi
Registration #2	2017-12-12	9.780 mi
Registration #3	2018-12-17	13.334 mi
Registration #4	2019-12-17	17.626 mi
Registration #5	2020-10-27	18.954 mi
Registration #6	2020-10-27	18.954 mi
Registration #7	2020-10-27	18.954 mi
Registration #8	2020-10-27	18.954 mi
Registration #9	2020-10-27	18.954 mi
Registration #10	2020-10-27	18.954 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	930 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Engine number	K10BN 1754073