





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOUAREG V6 R-LINE PLUS TDI BLUEMOTION
Colour	Black
Year of manufacture	2017
Top speed	140 mph
0 - 100 km/h	7.3 seconds
0 - 60 mph	7.3 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	193 kW / 263 HP / 258 BHP
Max. torque	580 Nm at 1.750 rpm
Engine capacity	2.967 сс
Cylinders	6
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	45.6 mpg
Consumption combined	41.5 mpg
CO2 emission	174 g/km
CO2 label	Н



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Er	ntr	v 3

Date	2021-10-23
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 2

Date	2021-10-05
Pictures	0
Listing price	View report

source: heycar.co.uk

Entry 1

y -	
Date	2021-10-04
Pictures	1
Listing price	View report



source: autotrader.co.uk

CarCheck.co.uk page 2/11



VO17UGB report date: 2024-03-28

MOT history

MOT expiry date	2025-01-29
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	10
Total items failed	1

MOT #7	2024-01-30 10:13
MOT test number	355975483407
Result	✓ Passed
Next expiry date	2025-01-29

MOT #6	2023-09-29 14:31
MOT test number	751746632342
Result	✓ Passed
Advice Nearside Front Outer Tyre slightly damaged (5.2.3 (d) (ii))	

MOT #5		2022-09-27 11:25
MOT test	number	231583807207
Result		✓ Passed
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #4		2021-10-08 08:29
MOT test	number	567164942534
Result		✓ Passed
MOT #3		2021-03-08 14:38
MOT test	number	489504094021
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #2	2020-03-17 15:11
MOT test number	198129714936
Result	√ Passed
MOT #1	2020-03-17 11:13
MOT test number	354084164784
Result	X Failed
Fail Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))	

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	29 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 5/11




report date: 2024-03-28

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



Extra VOLKSWAGEN salvage check



Category

Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



VO17UGB
report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dov here.	

Plate changes	More info >
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	OK SIN
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



VO17UGB report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2017-03-20
Last registration	2024-01-30
Complete history	See info



Registration #1	2017-03-20	21 mi
Registration #2	2020-03-17	36.863 mi
Registration #3	2020-03-17	36.863 mi
Registration #4	2021-03-08	44.339 mi
Registration #5		11.777 es
Registration #6		71.777 66
Registration #7		0.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		71.777 66
Registration #11		0.277 es

More info >

CarCheck.co.uk page 10/11



VO17UGB
report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2208 mm
Height	1732 mm
Length	4801 mm
Wheel base	2893 mm
Kerb weight	2085 kg
Max. allowed weight	2880 kg

Additional information

Fuel tank capacity	85 I
Fuel delivery	Direct Injection
Number of doors	5
CarChaelesaule	nama 11/11

CarCheck.co.uk page 11/11

Number of axles	2
Engine number	CVVA062098