





General information

| Make | MINI | |
|---------------------|-------------------|--|
| Model | JOHN COOPER WORKS | |
| Colour | Black | |
| Year of manufacture | 2017 | |
| Top speed | 150 mph | |
| 0 - 60 mph | 6.6 seconds | |
| Gearbox | 6 speed Manual | |

Engine & fuel consumption

| Power | 231 BHP | | 231 BHP |
|-------------------------|---------------------|--|---------|
| Max. torque | 320 Nm at 4.800 rpm | | |
| Engine capacity | 1.998 cc | | |
| Cylinders | 4 | | |
| Fuel type | Petrol | | |
| Consumption city | 32.8 mpg | | |
| Consumption extra urban | 52.3 mpg | | |
| Consumption combined | 43.5 mpg | | |
| CO2 emission | 152 g/km | | |
| CO2 label | G | | |





Internet history

Entry 1

Date

Pictures

2022-07-08

25

Listing price

View report



source: cargurus.co.uk



MOT history

| MOT expiry date | 2024-07-15 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 6 |
| Failed MOT tests | 2 |
| Total advice items | 4 |
| Total items failed | 2 |

| MOT #8 | 2023-07-10 13:31 |
|------------------|------------------|
| MOT test number | 948993826626 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-15 |

| MOT #7 | 2022-07-16 10:52 |
|-----------------|------------------|
| MOT test number | 489961041589 |
| Result | ✓ Passed |

| MOT #6 | 2022-07-16 10:52 |
|-------------------------|---|
| MOT test number | 393792975374 |
| Result | × Failed |
| Pass with rectification | Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) |

| MOT #5 | 2022-05-30 11:13 |
|-----------------|------------------|
| MOT test number | 292616077792 |
| Result | ✓ Passed |

| MOT #4 | 2021-06-14 11:34 |
|--|------------------|
| MOT test number | 646879510040 |
| Result | 🗸 Passed |
| Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |





| MOT #3 | 2020-06-24 13:58 |
|--|-----------------------------|
| MOT test number | 999686274787 |
| Result | ✓ Passed |
| Advice Offside Front Outer Tyre has a cut but not deep enough to reach the plant | y or cords (5.2.3 (d) (i)) |
| MOT #2 | 2020-06-24 08:23 |
| MOT test number | 840756041270 |
| Result | 🗙 Failed |
| Fail (d) (ii))Nearside Front Outer Tyre has a bulge, caused by separation or partial fail | ure of its structure (5.2.3 |
| Advice Offside Front Outer Tyre has a cut but not deep enough to reach the pl | y or cords (5.2.3 (d) (i)) |
| | |
| MOT #1 | 2020-06-22 08:12 |
| MOT test number | 403101846913 |
| Result | ✓ Passed |
| Advice COVID-19 6 MONTH EXTENSION | |



Tax & MOT check

| √ Taxed | √ МОТ |
|-------------------------|--------------------------|
| Tax due: 1 July 2024 | Expires: 15 July 2024 |
| Tax status | Valid until 1 July |
| Days left | 62 |
| MOT expiry date | 15 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | 1 |
| First licence fee (12 months) | £ 645,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPL |
| Date | |
| Date | OLE |
| Category | E.S. |
| Туре | |

Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| ************ | |
| ******** | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this MINI had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Carrent registration | |
| Plate since | |
| | More info > |





Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 9 |
| First mileage registration | 2017-06-30 |
| Last registration | 2023-07-10 |
| Complete history | <u>See info</u> |



| Registration #1 | 2017-06-30 | 12 mi |
|-----------------|------------|------------|
| Registration #2 | 2020-06-24 | 9.903 mi |
| Registration #3 | 2020-06-24 | 9.904 mi |
| Registration #4 | 2021-06-14 | 14.137 mi |
| Registration #5 | 2022-05-30 | 19.353 mi |
| Registration #6 | | 11.177 esi |
| Registration #7 | | 11.777 esi |
| Registration #8 | | 11.177 esi |
| Registration #9 | | 11.777 esi |

More info >






Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| 50482 | |
| S0501 | |
| \$0566 | |
| \$0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 79% |
| Children | 73% |
| Pedestrian | 66% |
| Safety systems | 56% |
| Overall rating | 71% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1727 mm |
| Height | 1415 mm |
| Length | 3874 mm |
| Wheel base | 2495 mm |
| Kerb weight | 1310 kg |
| Max. allowed weight | 1770 kg |
| Additional information | |
| Fuel tank capacity | 44 |
| Fuel delivery | Direct Injection |
| Number of doors | 2 |
| Number of seats CarCheck.co.uk | 4 page 11/11 |