





report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	B-CLASS B180 CDI BLUEEFFICIENCY SPORT
Colour	White
Year of manufacture	2013
Top speed	118 mph
0 - 60 mph	11.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg
CO2 emission	117 g/km
CO2 label	С



CarCheck.co.uk page 1/13



Internet history

Entry 3

Date 2024-04-19

Pictures 9

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Date	2021-07-15

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-07-13	
Pictures	0	
Listing price	<u>View report</u>	

source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-04-14
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	32
Total items failed	3

MOT #11	2024-04-15 14:45
MOT test number	588863679563
Result	✓ Passed
Next expiry date	2025-04-14
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) Advice Offside door mirror housing damaged	

MOT #10		2023-05-23 15:02
MOT test	number	251969256915
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	

CarCheck.co.uk page 3/13



MOT #9 2023-05-23 09:03

MOT test number 842794515531

Result × Failed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8 2022-06-06 09:07

MOT test number 526205078384

Result

Passed

Minor Central Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #7 2021-07-19 10:29

MOT test number 166118840124

Result \(\sqrt{Passed} \)

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

CarCheck.co.uk page 4/13



MOT test number

190837606804

Result

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT #5

MOT test number

900502768685

Result

Advice

Road wheel slightly distorted Both front wheels are buckled. (5.2.2 (c) (i))

Minor

Windscreen damaged but not adversely affecting driver's view Stone chip. (3.2 (a) (i))

MOT #4 2018-09-28 15:30

MOT test number 799344552396

Result ✓ Passed

MOT #3

MOT test number

160030894681

Result

✓ Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 5/13



MOT test number
917973241496

Result
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Brake pipes not fully inspected due to under panels fitted

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Rear seat belt not fully inspected due to child seat fitted

MOT #1 2016-11-10 13:37 **MOT** test number 182058415297 × Failed Result **Advice** Brake pipes not fully inspected due to under panels fitted Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Advice Front Brake pad(s) wearing thin (3.5.1g) **Advice** Offside Rear seat belt not fully inspected due to child seat fitted Fail Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b) **Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/13



Tax & MOT check





Tax status	Expired at 15 February 2024
Days left	74 days too late
MOT expiry date	14 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13



AO63PXJ

report date: 2024-03-28

Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the report here.	

More i	nto >
Plate changes	
riate enanges	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
	INTERE
Plate since	
Plate since	
More i	nfo >

CarCheck.co.uk page 10/13



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-11-18
Last registration	2024-04-15
Complete history	See info



Registration #1	2013-11-18	17 mi
Registration #2	2016-11-10	34.940 mi
Registration #3	2016-11-10	34.940 mi
Registration #4	2017-10-04	46.493 mi
Registration #5	2018-09-28	51.773 mi
Registration #6	2019-09-12	60.390 mi
Registration #7	2020-10-09	68.815 mi
Registration #8		11.777 es
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		9.777 es
Registration #12		11.777 es
Registration #13		91.777 esi
Registration #14		11.777 es
Registration #15		11.117 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	97%
Children	81%
Pedestrian	56%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2010 mm
Height	1542 mm
Length	4359 mm
Wheel base	2699 mm
Kerb weight	1475 kg
Max. allowed weight	2000 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack caluk	nago 12/12

CarCheck.co.uk page 13/13

Number of seats	5
Number of axles	2
Engine number	K9KF452D022666