




report date: 2024-03-28

General information

Make	VOLVO
Model	V70 D SE EU4
Colour	Blue
Year of manufacture	2005
Top speed	130 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	160 BHP
Max. torque	340 Nm at 2.750 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-06-08
Pictures	12
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-18
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	9
Total items failed	11

MOT #21	2023-05-24 12:04
MOT test number	704429753049
Result	✓ Passed
Next expiry date	2024-06-18

MOT #20	2022-05-19 15:00
MOT test number	576861671636
Result	✓ Passed

MOT #19	2021-06-19 12:38
MOT test number	559508165242
Result	✓ Passed

MOT #18	2020-10-07 08:52
MOT test number	134291870524
Result	✓ Passed

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #17	2019-10-07 08:24
MOT test number	107403424722
Result	✓ Passed

**MOT #16** 2018-10-11 15:46**MOT test number** 581366059427**Result** ✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front wishbone bush (5.3.4 (a) (i))

Advice Nearside Rear tyre worn on outer edge

MOT #15 2018-10-11 08:58**MOT test number** 152549021043**Result** ✗ Failed

Advice Nearside Rear tyre worn on outer edge

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front wishbone bush (5.3.4 (a) (i))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #14 2017-10-03 15:09**MOT test number** 150136676599**Result** ✓ Passed**MOT #13** 2017-10-03 09:04**MOT test number** 887831949810**Result** ✗ Failed

Fail Offside rear parking brake recording little or no effort (3.7.B.6a)

Fail Parking brake: efficiency below requirements (3.7.B.7)

MOT #12 2016-10-11 14:12**MOT test number** 163186494493**Result** ✓ Passed

**MOT #11** 2016-10-10 08:57**MOT test number** 505689831872**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Front tyre worn inner edge**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**MOT #10** 2015-10-07 16:14**MOT test number** 483620949412**Result** ✓ Passed**MOT #9** 2015-10-06 08:32**MOT test number** 402797167313**Result** ✗ Failed**Fail** Registration plate lamp not working (1.1.C.1d)**Fail** Offside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement wish bone front bush (2.4.G.2)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Rear Exhaust system not adequately supported (7.1.1)**MOT #8** 2014-10-06 09:50**MOT test number** 968269274203**Result** ✓ Passed**MOT #7** 2013-10-08 10:17**MOT test number** 448101483292**Result** ✓ Passed

**MOT #6** 2012-09-27 09:38**MOT test number** 615851372200**Result** ✓ Passed**Notice** Tow ball/hitch not fitted at time of test**MOT #5** 2011-09-28 15:08**MOT test number** 337861371461**Result** ✓ Passed**MOT #4** 2011-09-28 09:28**MOT test number** 476721971213**Result** ✗ Failed**Fail** Rear Exhaust system not adequately supported (7.1.1)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #3** 2010-09-28 11:21**MOT test number** 123741870267**Result** ✓ Passed**MOT #2** 2009-09-16 08:58**MOT test number** 341299459475**Result** ✓ Passed**MOT #1** 2008-09-16 09:55**MOT test number** 740590468227**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
18 June 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	18 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	SP55ZTS
Plate since	2024-03-28
Current registration	SP55ZTS
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-09-30
Last registration	2023-05-24
Complete history	See info



Registration #1	2005-09-30	10 mi
Registration #2	2008-09-16	29.495 mi
Registration #3	2009-09-16	34.832 mi
Registration #4	2010-09-28	39.304 mi
Registration #5	2011-09-28	52.040 mi
Registration #6	2011-09-28	52.043 mi
Registration #7	2012-09-27	66.096 mi
Registration #8	2013-10-08	81.351 mi
Registration #9	2014-10-06	89.374 mi
Registration #10	2015-10-06	102.528 mi
Registration #11	2015-10-07	102.528 mi
Registration #12	2016-10-10	112.974 mi
Registration #13	2016-10-10	112.974 mi
Registration #14	2016-10-10	112.974 mi
Registration #15	2016-10-10	112.974 mi
Registration #16	2016-10-10	112.974 mi
Registration #17	2016-10-10	112.974 mi
Registration #18	2016-10-10	112.974 mi
Registration #19	2016-10-10	112.974 mi
Registration #20	2016-10-10	112.974 mi
Registration #21	2016-10-10	112.974 mi
Registration #22	2016-10-10	112.974 mi
Registration #23	2016-10-10	112.974 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1757 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	312942