

\$ SUZUKI



General information

| Make | SUZUKI |
|---------------------|----------------|
| Model | CELERIO SZ2 |
| Colour | Blue |
| Year of manufacture | 2016 |
| Top speed | 97 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 67 BHP | 0 < 101 A |
|-------------------------|--------------------|-------------|
| Max. torque | 90 Nm at 3.500 rpm | 101 - 120 B |
| Engine capacity | 996 cc | 121 - 140 P |
| Cylinders | 3 | 141 - 165 F |
| Fuel type | Petrol | 166 - 185 H |
| Consumption city | 55.4 mpg | 186 - 225 J |
| Consumption extra urban | 76.4 mpg | 225+ L |
| Consumption combined | 65.7 mpg | |
| CO2 emission | 99 g/km | |
| CO2 label | А | |
| | | |



| Internet history | |
|------------------|-------------|
| Entry 1 | |
| Date | 2021-02-04 |
| Pictures | 1 |
| Listing price | View report |



source: autoonline.co.uk



MOT history

| MOT expiry date | 2024-05-16 |
|--------------------|------------|
| MOT pass rate | 83 % |
| MOT passed | 5 |
| Failed MOT tests | 1 |
| Total advice items | 7 |
| Total items failed | 1 |

| MOT #6 | | 2023-05-04 09:58 |
|-----------|--|------------------|
| MOT test | number | 966685976921 |
| Result | | ✓ Passed |
| Next expi | ry date | 2024-05-16 |
| Advice | Unable to fully see front brake pads | |
| Advice | Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii)) | |
| Advice | Nearside Front Service brake binding but not excessively $(1.2.1 (f))$ | |
| Advice | Front Brake pad(s) wearing thin all (1.1.13 (a) (ii)) | |
| Advice | Offside Front Service brake binding but not excessively (1.2.1 (f)) | |

| MOT #5 | | 2022-05-12 09:46 |
|----------|--|------------------|
| MOT test | number | 929870079999 |
| Result | | ✓ Passed |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #4 | 2021-05-17 13:54 |
|-----------------|------------------|
| MOT test number | 609502923509 |
| Result | ✓ Passed |





| MOT #3 | 2020-04-01 08:22 |
|--|------------------|
| MOT test number | 457469261390 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2019-04-27 08:06 |
| MOT test number | 815436702468 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2019-04-18 10:46 |
| MOT test number | 522578624304 |
| Result | 🗙 Failed |
| Fail Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii)) | |



Tax & MOT check

| ✓ Taxed Tax due: 1 November 2024 | MOT Expires: 16 May 2024 |
|---|--------------------------------|
| Tax status | Valid until 1 November |
| Days left | 187 |
| MOT expiry date | 16 May 2024 |
| Full MOT history | See MOT history |
| Tax calculation | |
| Vehicle class | 48 |

| Band | A |
|---|----------------|
| Single payment (12 months) | £ 0,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |





Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPL |
| Date | |
| Date | OLE |
| Category | E.S. |
| Туре | |

Extra SUZUKI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.700 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ********** | |
|---|-------------|
| ******** | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this SUZUKI had different number plates. | |
| Number of plates | , |
| | |
| Current registration | |
| Carrent registration Foto since | |
| Current registration Fore since Current registration | |
| Carrent registration Fisto since Fato since Fisto since | 1000-01-01 |





Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 8 |
| First mileage registration | 2016-04-30 |
| Last registration | 2023-05-04 |
| Complete history | See info |



| Registration #1 | 2016-04-30 | 7 mi |
|-----------------|------------|------------|
| Registration #2 | 2019-04-18 | 45.798 mi |
| Registration #3 | 2019-04-27 | 46.034 mi |
| Registration #4 | 2020-04-01 | 56.676 mi |
| Registration #5 | | 11.777 mi |
| Registration #6 | | 11.777 esi |
| Registration #7 | | 11.777 mi |
| Registration #8 | | 11.777 esi |





Safety ratings

| NCAP rating | |
|----------------|-----------------|
| Adult | 61% |
| Children | 74% |
| Pedestrian | 68% |
| Safety systems | 38% |
| Overall rating | 60% |
| Video | see crash video |



| Dimensions & weight | |
|--|-------------------------------|
| Width | 1600 mm |
| Height | 1540 mm |
| Length | 3600 mm |
| Wheel base | 2425 mm |
| Kerb weight | 880 kg |
| Max. allowed weight | 1260 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 35 I |
| | 35 I Multi-Point Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Multi-Point Injection |
| Fuel tank capacity Fuel delivery Number of doors | Multi-Point Injection 5 |