





report date: 2024-03-29

General information

Make	HYUNDAI
Model	I40 CRDI STYLE
Colour	Red
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	12.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	138 BHP
Max. torque	325 Nm at 2.500 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-10-09

Pictures 9

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-12-01
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	11
Total items failed	1

MOT #8		2023-12-02 15:57
MOT test numb	per	497630807686
Result		✓ Passed
Next expiry da	te	2024-12-01
Advice Nea	rside headlamp light output weak and just legal	
Advice Rea	r Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #7		2022-10-18 10:56
MOT test	number	498692861388
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Inner Tyre worn close to legal limit/worn on edge both (5.2.3 (e))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))	

MOT #6		2021-09-07 14:46
MOT test	number	381377736618
Result		✓ Passed
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #5 2021-09-07 10:22

MOT test number 421805425863

Result X Failed

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #4 2020-09-01 12:31

MOT test number 140633772821

Result
✓ Passed

MOT #3 2019-08-06 12:58

MOT test number 878243127613

Result \rightarrow Passed

MOT #2 2018-08-02 09:44

MOT test number 625543449938

Result
✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1

(b) (i))

MOT #1 2017-08-16 10:52

MOT test number 258996653560

Result

Passed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 December
Days left	215
MOT expiry date	1 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

For how long did the current and previous owner(s) have this HYUNDAI? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	

THE STREET STREE	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-09-01
Last registration	2023-12-02
Complete history	See info



Registration #1	2014-09-01	11 mi
Registration #2	2017-08-16	46.192 mi
Registration #3	2018-08-02	62.333 mi
Registration #4	2019-08-06	81.568 mi
Registration #5	2020-09-01	88.200 mi
Registration #6		
Registration #6		
Registration #7		11.777 es
		11.777 es
Registration #7		11,777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4770 mm
Wheel base	2770 mm
Kerb weight	1659 kg
Max. allowed weight	2150 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1

Number of axles 2

Engine number D4FDEU415777