






report date: 2024-03-28

General information

| Make | CITROEN | |
|---------------------|---|--|
| Model | C4 GRAND PICASSO GRAND BLUEHDI FEEL S/S | |
| Colour | Blue | |
| Year of manufacture | 2017 | |
| Top speed | 117 mph | |
| 0 - 60 mph | 11.3 seconds | |
| Gearbox | 6 speed Manual | |

Engine & fuel consumption

| Power | 118 BHP |
|-------------------------|---------------------|
| Max. torque | 300 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 62.8 mpg |
| Consumption extra urban | 74.3 mpg |
| Consumption combined | 70.6 mpg |
| CO2 emission | 106 g/km |
| CO2 label | В |



CarCheck.co.uk page 1/11



YD67VWL

report date: 2024-03-28

Internet history

Entry 1

Date 2022-06-03

Pictures 20

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date | 2024-10-13 |
|--------------------|------------|
| MOT pass rate | 57 % |
| MOT passed | 4 |
| Failed MOT tests | 3 |
| Total advice items | 9 |
| Total items failed | 5 |

| MOT #7 | 2023-10-11 09:52 |
|------------------|------------------|
| MOT test number | 774642162072 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-13 |

| MOT #6 | 2022-10-04 14:46 |
|-----------------|------------------|
| MOT test number | 616184190169 |
| Result | ✓ Passed |

| MOT #5 | 2022-10-04 14:46 |
|--|---|
| MOT test number | 265864777174 |
| Result | X Failed |
| Pass with rectification all lamps (4.7.1 (b) (ii)) | Nearside Rear Registration plate lamp inoperative in the case of a single lamp or |

| MOT #4 | 2021-10-08 15:27 |
|-----------------|------------------|
| MOT test number | 321541992604 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



Result

YD67VWL report date: 2024-03-28

Passed

MOT #3 2021-10-08 08:30

MOT test number 980857790665

Result X Failed

Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

Fail Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm inner cords expossed (5.2.3 (e))

MOT #2 2020-10-14 16:25

MOT test number 283650585789

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Rear Lower Exhaust mounting defective (6.1.2 (a))

Advice Offside Front Seat belt slightly damaged (7.1.2 (b) (i))

MOT #1 2020-10-14 16:25

MOT test number 567224936776

Result × Failed

Advice Nearside Rear Lower Exhaust mounting defective (6.1.2 (a))

Pass with rectification Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Offside Front Seat belt slightly damaged (7.1.2 (b) (i))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 October |
|------------------|-----------------------|
| Days left | 156 |
| MOT expiry date | 13 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|--|------------|
| Band | F |
| First licence fee (12 months) | £ 185,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| * | | |
|--|-----------|-------|
| For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively. | | OEN |
| *************************************** | | |
| *************************************** | | |
| ************* | | |
| | | |
| | | |
| | | |
| | | |
| | More info | > |
| Plate changes See in this check if this CITROEN had different number plates. | | |
| Number of plates | | , |
| Current registration | UK UK | |
| Plate since | | 0.0.0 |
| Current registration | UK UK | |
| Plate since | | |
| | More info | > |
| | | |

CarCheck.co.uk page 8/11



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 9 |
| First mileage registration | 2017-09-08 |
| Last registration | 2023-10-11 |
| Complete history | See info |



| Registration #1 | 2017-09-08 | 11 mi |
|-----------------|------------|-----------|
| Registration #2 | 2020-10-14 | 37.621 mi |
| Registration #3 | 2020-10-14 | 37.621 mi |
| Registration #4 | 2021-10-08 | 49.337 mi |
| Registration #5 | 2021-10-08 | 49.337 mi |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | D.777 es |

More info >

CarCheck.co.uk page 10/11



Safety ratings

NCAP rating

Video <u>see crash video</u>

Dimensions & weight

| Width | 1826 mm |
|---------------------|---------|
| Height | 1644 mm |
| Length | 4597 mm |
| Wheel base | 2840 mm |
| Kerb weight | 1347 kg |
| Max. allowed weight | 2175 kg |

Additional information

| Fuel tank capacity | 55 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 7 |
| Number of axles | 2 |
| Engine number | JCAN3042659 |

CarCheck.co.uk page 11/11