





### General information

| Make                | VOLVO                |
|---------------------|----------------------|
| Model               | S40 R-DESIGN EDITION |
| Colour              | White                |
| Year of manufacture | 2011                 |
| Top speed           | 130 mph              |
| 0 - 60 mph          | 8.9 seconds          |
| Gearbox             | 5 speed Manual       |

### Engine & fuel consumption

| Power                   | 143 BHP             |
|-------------------------|---------------------|
| Max. torque             | 185 Nm at 4.500 rpm |
| Engine capacity         | 1.999 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 26.2 mpg            |
| Consumption extra urban | 49.6 mpg            |
| Consumption combined    | 37.2 mpg            |
| CO2 emission            | 176 g/km            |
| CO2 label               | I                   |





| Internet history |             |  |  |
|------------------|-------------|--|--|
| Entry 2          |             |  |  |
| Date             | 2021-11-12  |  |  |
| Pictures         | 1           |  |  |
| Listing price    | View report |  |  |
|                  |             |  |  |
|                  |             |  |  |



source: cargurus.co.uk

| Entry 1       |             |  |  |
|---------------|-------------|--|--|
| Date          | 2021-11-08  |  |  |
| Pictures      | 1           |  |  |
| Listing price | View report |  |  |



source: autotrader.co.uk



## MOT history

| MOT expiry date    | 2024-10-21 |
|--------------------|------------|
| MOT pass rate      | 91 %       |
| MOT passed         | 10         |
| Failed MOT tests   | 1          |
| Total advice items | 8          |
| Total items failed | 2          |

| MOT #11  | 2023-10-18 12:01 |
|--|------------------|
| MOT test number  | 945816167441     |
| Result   | ✓ Passed         |
| Next expiry date   | 2024-10-21       |
| Advice Offside Front Tyre worn close to legal limit/worn on edge Worn On Inner   | Edge (5.2.3 (e)) |
| Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush (5.3.4 (a) (i)) |                  |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge Worn On Inner I  | Edge (5.2.3 (e)) |

| 2022-10-19 11:00 |
|------------------|
| 754307252276     |
| ✓ Passed         |
|                  |

| МОТ #9  | 2022-10-17 10:10                    |
|---|-------------------------------------|
| MOT test number   | 342319854874                        |
| Result  | 🗙 Failed                            |
| <b>Fail</b> Stop lamp(s) not working high level (4.3.1 (a) (ii))            |                                     |
| Fail Offside Front Anti-roll bar ball joint dust cover no longer prevents t | he ingress of dirt (5.3.4 (b) (ii)) |

| MOT #8          | 2021-10-15 07:52 |
|-----------------|------------------|
| MOT test number | 359911068701     |
| Result          | ✓ Passed         |





| MOT #7   | 2020-10-06 13:36 |
|--|------------------|
| MOT test number  | 637614259902     |
| Result   | ✓ Passed         |
|  |                  |
| МОТ #6   | 2019-10-22 12:04 |
| MOT test number  | 123307885841     |
| Result   | ✓ Passed         |
|  |                  |
| MOT #5   | 2018-10-19 08:21 |
| MOT test number  | 363392265919     |
| Result   | ✓ Passed         |
|  |                  |
| МОТ #4   | 2017-10-13 09:58 |
| MOT test number  | 784092910860     |
| Result   | ✓ Passed         |
| Advice Items removed from driver's view prior to test                    |                  |
| Advice Offside Rear Direction indicators slightly discoloured (1.4.A.2f) |                  |

| MOT #3          | 2016-10-19 12:31 |
|-----------------|------------------|
| MOT test number | 208342945632     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #2          | 2015-10-10 11:58 |
| MOT test number | 605683654551     |

| MOT test number | 605683654551 |
|-----------------|--------------|
| Result          | ✓ Passed     |





| MOT #1   |   | 2014-10-20 15:19 |
|----------|---|------------------|
| MOT test | number  | 987583494238     |
| Result   |   | ✓ Passed         |
| Advice   | Offside Front Tyre worn close to the legal limit (4.1.E.1)                    |                  |
| Advice   | Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3 | 3.1a)            |
| Advice   | Nearside Front Tyre worn close to the legal limit (4.1.E.1)                   |                  |



Tax & MOT check

| √<br>Taxed                  | ✓<br>MOT                    |
|-----------------------------|-----------------------------|
| Tax due:<br>1 November 2024 | Expires:<br>21 October 2024 |
| Tax status                  | Valid until 1 November      |
| Days left                   | 186                         |
| MOT expiry date             | 21 October 2024             |
| Full MOT history            | See MOT history             |

## Tax calculation

| Vehicle class                           | 48         |
|---|------------|
| Band                                    | 1          |
| Single payment (12 months)              | £ 320,00,- |
| Single six month payment                | £ 176,00,- |
| Total payable by 12 monthly instalments | £ 336,00,- |





#### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |         |
|----------|---------|
| Date     |         |
| Category | Lampe   |
| Туре     |         |
| Damage 2 | AMPLE   |
| Damage 2 | E E E E |
| Date     | S.      |
| Category | ame     |
| Туре     |         |

#### Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4.11.111 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 11 711 |





## Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| and a second sec |             |
|--|-------------|
| ***********  |             |
| *******  |             |
| *******  |             |
| ***********  |             |
| ********   |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this VOLVO had different number plates.   |             |
| Number of plates   | ,           |
| Current registration   |             |
| Plate since  |             |
| Current registration   |             |
| Plate since  |             |
|  | More info > |





#### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |



P200MVS report date: 2024-03-29

# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 14         |
| First mileage registration | 2011-11-28 |
| Last registration          | 2023-10-18 |
| Complete history           | See info   |



| Registration #1  | 2011-11-28 | 7 mi       |
|------------------|------------|------------|
| Registration #2  | 2014-10-20 | 19.388 mi  |
| Registration #3  | 2015-10-10 | 36.942 mi  |
| Registration #4  | 2016-10-19 | 52.376 mi  |
| Registration #5  | 2017-10-13 | 60.590 mi  |
| Registration #6  | 2018-10-19 | 68.482 mi  |
| Registration #7  | 2019-10-22 | 73.152 mi  |
| Registration #8  |            | 11.777 esi |
| Registration #9  |            | 11.777 mi  |
| Registration #10 |            | 11.777 esi |
| Registration #11 |            | 11.777 mi  |
| Registration #12 |            | 11.777 esi |
| Registration #13 |            | 11.777 mi  |
| Registration #14 |            | 10.300 est |





#### Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

# Safety ratings

**NCAP** rating

Video

\*\*\*\* see crash video



| Dimensions & weight               |                       |
|-----------------------------------|-----------------------|
| Width                             | 1770 mm               |
| Height                            | 1454 mm               |
| Length                            | 4476 mm               |
| Wheel base                        | 2640 mm               |
| Kerb weight                       | 1379 kg               |
| Max. allowed weight               | 1850 kg               |
| Additional information            |                       |
| Fuel tank capacity                | 55 l                  |
| Fuel delivery                     | Multi-Point Injection |
| Number of doors                   | 4                     |
| Number of seats<br>CarCheck.co.uk | 5 page 12/12          |

| Number of axles | 2       |
|-----------------|---------|
| Engine number   | 1045425 |