



report date: 2024-03-29

General information

Make	VOLVO
Model	XC60 D3 SE LUX AWD
Colour	Silver
Year of manufacture	2012
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	41.5 mpg
CO2 emission	179 g/km
CO2 label	I





## MOT history

MOT expiry date	2020-11-15
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	14
Total items failed	3

MOT #8	2019-11-13 11:49
MOT test number	763620905068
Result	✓ Passed
Next expiry date	2020-11-15
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Rear tyres going lumpy
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7	2018-11-13 12:49
MOT test number	585001818624
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6	2018-11-13 11:34
MOT test number	800629494022
Result	✗ Failed
DANGEROUS	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
DANGEROUS	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #5** 2017-11-08 10:02**MOT test number** 369130264499**Result** ✓ Passed**MOT #4** 2016-11-08 16:17**MOT test number** 198538384104**Result** ✓ Passed**MOT #3** 2016-11-08 12:22**MOT test number** 884927482833**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2015-11-16 16:40**MOT test number** 950296817911**Result** ✓ Passed**Advice** O/s/f tyre cut but not more than 25mm in tread**Advice** Front brake disc worn, pitted or scored, but not seriously weakened lipped (3.5.1i)**MOT #1** 2015-01-22 14:49**MOT test number** 425442525052**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✕  
Untaxed

Tax expired:  
24 May 2020

✕  
MOT

Expired:  
15 November 2020

Tax status	Expired at 24 May 2020
Days left	1436 days too late
MOT expiry date	15 November 2020
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>GL61FPN</b>
Plate since	2019-03-29
Current registration	<b>GL61FPN</b>
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >





Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2012-01-19
Last registration	2019-11-13
Complete history	<a href="#">See info</a>



Registration #1	2012-01-19	27 mi
Registration #2	2015-01-22	43.272 mi
Registration #3	2015-11-16	59.497 mi
Registration #4	2016-11-08	78.589 mi
Registration #5	2016-11-08	78.589 mi
Registration #6	2019-11-13	78.589 mi
Registration #7	2019-11-13	78.589 mi
Registration #8	2019-11-13	78.589 mi
Registration #9	2019-11-13	78.589 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1861 mm
Height	1604 mm
Length	4838 mm
Wheel base	2815 mm
Kerb weight	1891 kg
Max. allowed weight	2400 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1133407