





General information

| Make | PEUGEOT |
|---------------------|----------------|
| Model | 508 HDI SW SR |
| Colour | Black |
| Year of manufacture | 2011 |
| Top speed | 138 mph |
| 0 - 60 mph | 9.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 163 BHP |
|-------------------------|---------------------|
| Max. torque | 340 Nm at 2.000 rpm |
| Engine capacity | 1.997 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 42.2 mpg |
| Consumption extra urban | 70.6 mpg |
| Consumption combined | 56.5 mpg |
| CO2 emission | 130 g/km |
| CO2 label | D |





Internet history

| Entry | 1 |
|-------|---|
| | |

Date Pictures 2021-12-01

Listing price

View report

8



source: autotrader.co.uk



MOT history

| MOT expiry date | 2025-03-03 |
|--------------------|------------|
| MOT pass rate | 85 % |
| MOT passed | 11 |
| Failed MOT tests | 2 |
| Total advice items | 25 |
| Total items failed | 3 |

| MOT #13 | 2024-03-01 14:56 |
|--|------------------|
| MOT test number | 863509374328 |
| Result | Passed |
| Next expiry date | 2025-03-03 |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice Under trays fitted | |
| Advice Oil leak, but not excessive (8.4.1 (a) (i)) | |
| Advice Engine covers fitted | |

MOT #12

2023-03-01 13:12

| MOT test | number | 786096413110 |
|----------|---|--------------|
| Result | | ✓ Passed |
| Advice | Under trays fitted | |
| Advice | Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e)) | |
| Advice | Engine covers fitted | |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) | |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |





| MOT #11 | 2022-03-03 11:15 |
|----------|--|
| MOT test | number 580738262443 |
| Result | ✓ Passed |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge inner & outer edges (5.2.3 (e)) |

| МОТ #10 | 2021-03-01 17:28 |
|---|------------------|
| MOT test number | 164334751840 |
| Result | ✓ Passed |
| Minor Nearside Front Tyre obviously under inflated (5.2.3 (I)) | |
| Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice Oil leak, but not excessive (8.4.1 (a) (i)) | |

| МОТ #9 | 2020-02-27 17:55 |
|---|------------------|
| MOT test number | 615019732705 |
| Result | ✓ Passed |
| Advice Both front link boots are insecure | |

| MOT #8 | 2020-02-27 11:33 |
|---|------------------------|
| MOT test number | 245603730516 |
| Result | 🗙 Failed |
| Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii)) | |
| Advice Both front link boots are insecure | |
| Fail Offside Registration plate lamp does not illuminate simultaneously with the positive | tion lamps (4.7.2 (a)) |
| Advice N/s/f tyre has cuts on outer wall | |





| MOT #7 | | 2019-03-04 12:16 |
|----------|--|------------------|
| MOT test | number | 969803048964 |
| Result | | ✓ Passed |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| | | |
| MOT #6 | | 2019-03-04 10:07 |
| MOT test | number | 153043955023 |
| Result | | 🗙 Failed |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Rear Brake pad(s) wearing thin both (1.1.13 (a) (ii)) | |
| Fail N | earside Rear Brake cable has restricted free movement bracket broken (1.1.15 (e) |) |

| MOT #5 | 2018-03-02 10:15 |
|-----------------|------------------|
| MOT test number | 832436678005 |
| Result | ✓ Passed |

| MOT #4 | 2017-05-09 16:23 |
|-----------------|------------------|
| MOT test number | 921854554854 |
| Result | ✓ Passed |

| MOT #3 | 2016-03-01 14:10 |
|--|------------------|
| MOT test number | 853280119995 |
| Result | ✓ Passed |
| Advice Steering system slightly tight on lock to lock turn (2.2.D.1) | |





| MOT #2 | | 2015-04-04 14:51 |
|----------|---|------------------|
| MOT test | number | 168554695409 |
| Result | | ✓ Passed |
| Notice | N/S/R tyre tread uneven | |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| | | |

| MOT #1 | 2014-04-12 12:11 |
|-----------------|------------------|
| MOT test number | 895202504184 |
| Result | ✓ Passed |



Tax & MOT check

| Tax due: 1 January 2025 | ✓ Taxed | Expires: 3 March 2025 | ✓ мот |
|-----------------------------------|------------|---------------------------------|-----------------------|
| Tax status | | | Valid until 1 January |
| Days left | | | 247 |
| MOT expiry date | | | 3 March 2025 |
| Full MOT history | | | See MOT history |
| Tax calculation | | | |

| Vehicle class | 49 |
|----------------------------|------------|
| Band | D |
| Single payment (12 months) | £ 150,00,- |

| Single six month payment | £ 82,50,- |
|---|------------|
| Total payable by 12 monthly instalments | £ 157,50,- |





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---|
| Date | |
| Category | 4. DEM PE |
| Туре | |
| Damage 2 | Annet |
| Date | No. Contraction of the second |
| Category | AMP |
| Туре | |

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 6.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 11 711 |





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| xxxxxxxx | |
|--|-------------|
| *********** | |
| ******* | |
| ****** | |
| ********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this PEUGEOT had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 15 |
| First mileage registration | 2011-04-18 |
| Last registration | 2024-03-01 |
| Complete history | <u>See info</u> |



| Registration #1 | 2011-04-18 | 13 mi |
|------------------|------------|------------|
| Registration #2 | 2014-04-12 | 54.434 mi |
| Registration #3 | 2015-04-04 | 73.520 mi |
| Registration #4 | 2016-03-01 | 85.331 mi |
| Registration #5 | 2017-05-09 | 100.126 mi |
| Registration #6 | 2018-03-02 | 106.300 mi |
| Registration #7 | 2019-03-04 | 112.091 mi |
| Registration #8 | 2019-03-04 | 112.091 mi |
| Registration #9 | | 11.777 esi |
| Registration #10 | | 11.777 esi |
| Registration #11 | | 11.777 esi |
| Registration #12 | | 11.777 esi |
| Registration #13 | | 11.777 esi |
| Registration #14 | | 11.777 esi |
| Registration #15 | | 11.777 mi |





Car features

| 50225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 90% |
| Children | 87% |
| Pedestrian | 41% |
| Safety systems | 97% |
| Overall rating | 80% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1853 mm |
| Height | 1476 mm |
| Length | 4813 mm |
| Wheel base | 2817 mm |
| Kerb weight | 1710 kg |
| Max. allowed weight | 2140 kg |
| Additional information | |
| Fuel tank capacity | 72 |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 13/13 |

| Number of axles | 2 |
|-----------------|-------------|
| Engine number | DYYF4077053 |