



report date: 2024-03-29

General information

Make	FORD
Model	FUSION STYLE CLIMATE
Colour	Purple
Year of manufacture	2008
Top speed	102 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-03-09
Pictures	27
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT expiry date	2024-12-06
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	28
Total items failed	2

MOT #17 2023-12-07 11:37**MOT test number** 780627520689**Result** Passed**Next expiry date** 2024-12-06**Advice** Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #16** 2022-12-06 11:44**MOT test number** 640150196725**Result** Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))**MOT #15** 2021-11-23 12:35**MOT test number** 183826893484**Result** Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #14** 2020-11-24 12:14**MOT test number** 188710733093**Result** ✓ Passed**MOT #13** 2019-11-21 15:07**MOT test number** 364470603771**Result** ✓ Passed**MOT #12** 2019-11-21 11:43**MOT test number** 365618020133**Result** ✗ Failed**MAJOR** Offside Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))**DANGEROUS** Offside Front Tyre has ply or cords exposed In tread (5.2.3 (d) (ii))**MAJOR** Nearside Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))**DANGEROUS** Nearside Front Tyre has ply or cords exposed In tread (5.2.3 (d) (ii))**MOT #11** 2018-11-22 12:27**MOT test number** 886732834290**Result** ✓ Passed**Advice** Nearside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Front Tyre has cuts in tread**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre has cuts in tread

**MOT #10** 2017-11-23 11:38**MOT test number** 184608992920**Result** ✓ Passed**Advice** Offside Rear Tyre starting to perish**Advice** Nearside Rear Tyre has cuts in tread**MOT #9** 2016-11-21 14:51**MOT test number** 849056346548**Result** ✓ Passed**MOT #8** 2016-11-21 09:52**MOT test number** 190109225685**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #7** 2015-11-20 10:41**MOT test number** 850532214183**Result** ✓ Passed**Advice** Rear tyres perishing**MOT #6** 2014-11-17 11:55**MOT test number** 915761124336**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #5** 2013-11-19 11:46**MOT test number** 425723423402**Result** ✓ Passed

**MOT #4** 2012-12-04 12:55**MOT test number** 506619232398**Result** ✓ Passed**MOT #3** 2012-03-23 14:30**MOT test number** 647863282079**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Front wipers beginning to smear/judder across screen**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Condensation in both rear lamps**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2012-03-23 14:30**MOT test number** 907103482017**Result** ✗ Failed**Notice** Front wipers beginning to smear/judder across screen**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Condensation in both rear lamps**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2011-04-21 12:07**MOT test number** 415031411189**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
6 December 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	6 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-05-30
Last registration	2023-12-07
Complete history	See info



Registration #1	2008-05-30	24 mi
Registration #2	2011-04-21	14.539 mi
Registration #3	2012-03-23	18.136 mi
Registration #4	2012-12-04	20.192 mi
Registration #5	2013-11-19	23.580 mi
Registration #6	2014-11-17	28.653 mi
Registration #7	2015-11-20	32.321 mi
Registration #8	2016-11-21	36.786 mi
Registration #9	2016-11-21	36.786 mi
Registration #10	2016-11-21	36.786 mi
Registration #11	2016-11-21	36.786 mi
Registration #12	2016-11-21	36.786 mi
Registration #13	2016-11-21	36.786 mi
Registration #14	2016-11-21	36.786 mi
Registration #15	2016-11-21	36.786 mi
Registration #16	2016-11-21	36.786 mi
Registration #17	2016-11-21	36.786 mi
Registration #18	2016-11-21	36.786 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1199 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	8A48618