



TOYOTA




report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VVTI T SPIRIT
Colour	Silver
Year of manufacture	2006
Top speed	118 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	150 Nm at 3.800 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	47.8 mpg
Consumption combined	40.3 mpg
CO2 emission	168 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-06-27
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-01
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	62
Total items failed	2

MOT #172023-07-13 13:38

MOT test number277924677193

Result✓ Passed

Next expiry date2024-08-01

- AdviceRear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- AdviceNearside Rear Coil spring corroded (5.3.1 (b) (i))
- AdviceCentral Front Items removed from driver's view prior to test
- AdviceNearside Rear Outer Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- AdviceOffside Rear Child Seat fitted not allowing full inspection of adult belt
- AdviceOffside Rear Coil spring corroded (5.3.1 (b) (i))
- AdviceNearside Rear Child Seat fitted not allowing full inspection of adult belt
- AdviceOffside Rear Outer Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #16**

2023-07-11 11:39

MOT test number

608226122393

Result**✗ Failed****MAJOR** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm 195/60rr15 88v (5.2.3 (e))**Advice** Offside Rear Outer Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Central Front Items removed from driver's view prior to test**MAJOR** Nearside Front Lower Bumper insecure trim (6.1.4 (a) (i))**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Outer Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**DANGEROUS** Offside Rear Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Nearside Front Headlamp aim projected beam image is obviously incorrect headlight damaged (4.1.2 (c))

**MOT #15**

2022-08-02 13:46

MOT test number

904144284815

Result

✓ Passed

- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Outer Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Outer Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #14

2021-07-24 13:36

MOT test number

753071400409

Result

✓ Passed

- Advice** Suspension arm pin or bush worn but not resulting in excessive movement both front (5.3.4 (a) (i))
- Advice** General surface corrosion to underneath
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Coil spring corroded both rear (5.3.1 (b) (i))

**MOT #13**

2021-07-02 16:25

MOT test number

224446719694

Result**✗ Failed**

- Advice** Front brakes binding
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- MAJOR** Nearside Rear Upper Coil spring mounting corroded and seriously weakened (5.3.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- MAJOR** Offside Rear Upper Coil spring mounting corroded and seriously weakened (5.3.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12

2019-04-02 13:19

MOT test number

638825921424

Result**✓ Passed**

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #11**

2018-04-04 14:25

MOT test number

573141961160

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Advice** Rear Sub-frame corroded but not seriously weakened (2.4.G.1)
- Advice** Offside Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear coil spring corroded (2.4.C.1b)

MOT #10

2017-04-07 12:58

MOT test number

202431378451

Result

✓ Passed

MOT #9

2017-04-06 11:52

MOT test number

957105956131

Result

✗ Failed

- Fail** Offside Front Lower Suspension arm corroded and seriously weakened (2.4.G.1)
- Fail** Nearside Front Lower Suspension arm corroded and seriously weakened (2.4.G.1)

MOT #8

2016-03-30 13:33

MOT test number

465073103481

Result

✓ Passed

- Advice** Nearside Front Suspension arm corroded but not seriously weakened (2.4.G.1)
- Advice** Centre Rear Sub-frame corroded but not seriously weakened (2.4.G.1)
- Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (2.4.G.1)

**MOT #7** 2015-03-21 11:35**MOT test number** 708150685042**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-03-28 13:50**MOT test number** 228207384024**Result** ✓ Passed**MOT #5** 2013-04-02 16:18**MOT test number** 995222293098**Result** ✓ Passed**MOT #4** 2012-03-24 10:07**MOT test number** 767754482048**Result** ✓ Passed**MOT #3** 2011-04-08 13:02**MOT test number** 396978691019**Result** ✓ Passed**MOT #2** 2010-04-13 12:53**MOT test number** 671003500125**Result** ✓ Passed**MOT #1** 2009-04-15 11:29**MOT test number** 220805909414**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
1 August 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	1 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-06-13
Last registration	2023-07-13
Complete history	See info



Registration #1	2006-06-13	13 mi
Registration #2	2009-04-15	35.623 mi
Registration #3	2010-04-13	37.302 mi
Registration #4	2011-04-08	39.093 mi
Registration #5	2012-03-24	40.626 mi
Registration #6	2013-04-02	42.892 mi
Registration #7	2014-03-28	44.469 mi
Registration #8	2015-03-21	46.049 mi
Registration #9	2016-03-30	47.669 mi
Registration #10	2017-04-06	48.814 mi
Registration #11	2018-04-06	50.000 mi
Registration #12	2019-04-06	51.200 mi
Registration #13	2020-04-06	52.400 mi
Registration #14	2021-04-06	53.600 mi
Registration #15	2022-04-06	54.800 mi
Registration #16	2023-04-06	56.000 mi
Registration #17	2024-04-06	57.200 mi
Registration #18	2025-04-06	58.400 mi
Registration #19	2026-04-06	59.600 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1220 kg
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	3ZZU778649