





report date: 2024-03-29

### General information

Make	FORD
Model	S-MAX TITANIUM
Colour	Grey
Year of manufacture	-
Top speed	120 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed automatic

### Engine & fuel consumption

Power	159 BHP
Cylinders	4
Fuel type	Petrol
Consumption city	20.6 mpg
Consumption extra urban	38.2 mpg
Consumption combined	29.1 mpg



CarCheck.co.uk page 1/12



# Internet history

### Entry 1

Date 2021-08-11

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT #14		2021-07-07 17:00
MOT test number		684061620551
Result		✓ Passed
Next expiry date		2022-07-06
MOT #13		2020-07-02 15:29
MOT test number		237724916571
Result		✓ Passed
MOT #12		2020-07-02 15:29
MOT test number		162403117232
Result		<b>X</b> Failed
Pass with rectification	Central Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #11		2018-06-07 15:29
MOT test	number	800201005592
Result		<b>✓</b> Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Suspension component pin or bush slightly worn trailing arm	bush (5.3.4 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



**MOT #10** 2018-06-07 11:26

**MOT test number** 367029094695

**Result** X Failed

**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))

Fail Nearside Rear Suspension component pin or bush excessively worn trailing arm bush (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))

**Fail** Central Exhaust system insecure (6.1.2 (a))

Advice Offside Rear Suspension component pin or bush slightly worn trailing arm bush (5.3.4 (a) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #9 2017-06-13 14:05

**MOT test number** 885497575895

**Result** ✓ Passed

**MOT #8** 2017-06-07 10:26

MOT test number 931353547356

**Result** X Failed

Advice High level brake light not working

**Fail** Offside Front position lamp(s) not working (1.1.A.3b)

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)

**Advice** Offside Front tyre wearing on inner edge (225/50/17)

Fail Offside Rear Seat belt locking mechanism does not secure or release middle row (5.2.5a)

CarCheck.co.uk page 4/12



MOT #7 2016-05-13 12:01

MOT test number 634165866944

**Result** ✓ Passed

Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

**Advice** Nearside Rear coil spring corroded (2.4.C.1b)

Advice Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

**Advice** Offside Rear coil spring corroded (2.4.C.1b)

MOT #6 2015-05-06 11:21

MOT test number 765596625113

**Result** 
✓ Passed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2014-05-01 15:12

**MOT test number** 779931824189

Result \( \sqrt{Passed} \)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #4 2014-05-01 10:15

**MOT test number** 275881924460

Result X Failed

Advice Front Brake pad(s) wearing thin (3.5.1g)

**Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

CarCheck.co.uk page 5/12



MOT #3		2013-04-29 11:55
MOT test	number	979649613156
Result		<b>✓</b> Passed
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)	

MOT #2		2012-04-24 10:32
MOT test	number	458525612185
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #1	2011-04-13 08:52
MOT test number	756023801129
Result	✓ Passed

CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

*		
For how long did the current and previous owner(s) have this FORD? How many owners defect it in the premium report and see all owner registrations. Download the full report is		ave?
********		
***************************************		
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		,
Current registration	UK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-29

#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



# Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-04-29
Last registration	2021-07-07
Complete history	See info



Registration #1	2008-04-29	16 mi
Registration #2	2011-04-13	20.316 mi
Registration #3	2012-04-24	28.094 mi
Registration #4	2013-04-29	36.909 mi
Registration #5	2014-05-01	45.467 mi
Registration #6	2014-05-01	45.467 mi
Registration #7	2015-05-06	53.713 mi
Registration #8	2016-05-13	61.690 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		9.277 es
Registration #14		0.00 44
Registration #15		0.074
Registration #16		11.777 es

More info >

CarCheck.co.uk page 11/12



### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Max. allowed weight	2405 kg

# Additional information

Fuel tank capacity	70
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Engine number CarCheck.co.uk	8A80541 page 12/12