




report date: 2024-03-28

## General information

Make	VOLVO
Model	S40 S S40
Colour	Silver
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	99 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.2 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-08-30
Pictures	11
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-07-03
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	2
Total items failed	8

MOT #15	2023-06-20 09:51
MOT test number	821216356248
Result	✓ Passed
Next expiry date	2024-07-03

MOT #14	2023-06-20 08:31
MOT test number	430602179617
Result	✗ Failed
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #13	2022-06-28 11:16
MOT test number	787831894858
Result	✓ Passed

MOT #12	2021-06-08 08:41
MOT test number	382753191427
Result	✓ Passed

MOT #11	2020-07-04 14:18
MOT test number	270527440971
Result	✓ Passed

**MOT #10** 2020-06-29 12:50**MOT test number** 325462725538**Result** ✗ Failed**Advice** Rear Direction indicator slightly discoloured Both sides (OSR & NSR). (4.4.3 (a))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing 205/50/17 (5.2.3 (d) (ii))**Fail** Nearside Rear Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Also tyre perished, and nail at the thread. (5.2.3 (d) (i))**MOT #9** 2019-07-02 09:57**MOT test number** 325342044829**Result** ✓ Passed**MOT #8** 2019-07-01 14:19**MOT test number** 672719050335**Result** ✗ Failed**Fail** Offside Rear fog lamp not working (4.5.1 (a) (ii))**Pass with rectification** Offside Front Bumper insecure (6.1.4 (a) (i))**Fail** Offside Side repeater not working (4.4.1 (a) (ii))**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #7** 2017-09-15 14:32**MOT test number** 384161626935**Result** ✓ Passed**MOT #6** 2016-08-30 12:09**MOT test number** 858279465561**Result** ✓ Passed



MOT #5	2015-09-29 16:06
MOT test number	236060948923
Result	✓ Passed
MOT #4	2015-09-22 15:40
MOT test number	258838931735
Result	✗ Failed
<div><div>Fail</div>Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)</div>	
MOT #3	2014-09-08 16:59
MOT test number	385071954237
Result	✓ Passed
MOT #2	2013-09-12 15:01
MOT test number	886475253293
Result	✓ Passed
MOT #1	2012-08-23 12:59
MOT test number	939206932238
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
3 July 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	3 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-10-09
Last registration	2023-06-20
Complete history	<a href="#">See info</a>



Registration #1	2009-10-09	15 mi
Registration #2	2012-08-23	5.897 mi
Registration #3	2013-09-12	7.823 mi
Registration #4	2014-09-08	9.443 mi
Registration #5	2015-09-22	10.847 mi
Registration #6	2015-09-29	10.883 mi
Registration #7	2016-08-30	11.816 mi
Registration #8	2017-09-15	12.802 mi
Registration #9	2019-07-01	13.244 mi
Registration #10	2020-06-20	13.244 mi
Registration #11	2020-06-20	13.244 mi
Registration #12	2020-06-20	13.244 mi
Registration #13	2020-06-20	13.244 mi
Registration #14	2020-06-20	13.244 mi
Registration #15	2020-06-20	13.244 mi
Registration #16	2020-06-20	13.244 mi
Registration #17	2020-06-20	13.244 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1322 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	180553