



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	IQ VVT-I IQ2
Colour	Red
Year of manufacture	2012
Top speed	93 mph
0 - 60 mph	15.3 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	67 BHP
Max. torque	91 Nm at 4.800 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	58.9 mpg
CO2 emission	110 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-09-14
Pictures	40
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-03
MOT pass rate	100 %
MOT passed	10
Failed MOT tests	0
Total advice items	10
Total items failed	0

MOT #10	2023-09-27 08:43
MOT test number	261913253943
Result	✓ Passed
Next expiry date	2024-10-03
Minor	Offside Front Side repeater with a multiple light source up to 1/2 not functioning repeater working but light not travelling along the full length of the mirror casing (4.4.1 (a) (i))

MOT #9	2022-09-22 08:31
MOT test number	959400664948
Result	✓ Passed
Advice	Corrosion to front subframe

MOT #8	2021-09-08 07:34
MOT test number	300272555955
Result	✓ Passed

**MOT #7** 2020-09-15 12:00**MOT test number** 520121344718**Result** ✓ Passed**Advice** Tyre slightly damaged/cracking or perishing ALL TYRES HAVE CRACKS (5.2.3 (d) (ii))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**MOT #6** 2019-09-20 08:39**MOT test number** 566619202074**Result** ✓ Passed**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Rear Tyre slightly damaged/cracking or perishing both rear tyre outer sidewalls/edges & through tread (5.2.3 (d) (ii))**Advice** Front Tyre slightly damaged/cracking or perishing both front tyre outer sidewalls/edges (5.2.3 (d) (ii))**MOT #5** 2018-09-25 09:37**MOT test number** 775198033362**Result** ✓ Passed**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**MOT #4** 2017-09-27 11:23**MOT test number** 281366274272**Result** ✓ Passed**MOT #3** 2016-10-04 14:43**MOT test number** 479991304215**Result** ✓ Passed



MOT #2	2015-11-30 10:28
MOT test number	824319793293
Result	✓ Passed
MOT #1	2015-01-22 15:09
MOT test number	308062725012
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
3 October 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	3 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	CX12VWH
Plate since	2019-03-29
Current registration	CX12VWH
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-03-12
Last registration	2023-09-27
Complete history	See info



Registration #1	2012-03-12	24 mi
Registration #2	2015-01-22	3.398 mi
Registration #3	2015-11-30	5.444 mi
Registration #4	2016-10-04	7.410 mi
Registration #5	2017-09-27	8.401 mi
Registration #6	2018-09-25	10.488 mi
Registration #7	2019-09-27	12.575 mi
Registration #8	2020-09-27	14.662 mi
Registration #9	2021-09-27	16.749 mi
Registration #10	2022-09-27	18.836 mi
Registration #11	2023-09-27	20.923 mi
Registration #12	2024-03-29	24 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	71%
Pedestrian	54%
Safety systems	86%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1680 mm
Height	1500 mm
Length	2985 mm
Wheel base	2000 mm
Kerb weight	845 kg
Max. allowed weight	1215 kg

Additional information

Fuel tank capacity	32 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1KR1343429