



report date: 2024-03-29

General information

Make	CITROEN
Model	C5 VTR PLUS HDI
Colour	Grey
Year of manufacture	-
Top speed	138 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	60.1 mpg
Consumption combined	50.4 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-11-16
Pictures	16
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT #17</b>	2022-10-19 17:02
<b>MOT test number</b>	427451023134
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-10-18
<b>Advice</b>	Nearside Oil leak, but not excessive Drive shaft seal (8.4.1 (a) (i))
<b>Advice</b>	Nearside Rear Tyre slightly damaged/cracking or perishing edges and in tread area (5.2.3 (d) (ii))

<b>MOT #16</b>	2022-10-11 18:02
<b>MOT test number</b>	975142494346
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside Oil leak, but not excessive Drive shaft seal (8.4.1 (a) (i))
<b>Advice</b>	Nearside Rear Tyre slightly damaged/cracking or perishing edges and in tread area (5.2.3 (d) (ii))
<b>Fail</b>	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
<b>Fail</b>	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

<b>MOT #15</b>	2021-12-02 12:27
<b>MOT test number</b>	252779701237
<b>Result</b>	✓ Passed

<b>MOT #14</b>	2021-11-26 11:25
<b>MOT test number</b>	720259949221
<b>Result</b>	✗ Failed
<b>Minor</b>	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
<b>Fail</b>	Road wheel fixing missing on each wheel (5.2.1 (a) (i))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge on inner edge (5.2.3 (e))



<b>MOT #13</b>	2020-10-13 13:48
<b>MOT test number</b>	479271737922
<b>Result</b>	✓ Passed
<b>Advice</b>	Front Undertray not fully secure (8.1.1 (b) (i))
<b>Advice</b>	O/S front outer CV gaiter is leaking grease slightly

<b>MOT #12</b>	2019-09-25 14:53
<b>MOT test number</b>	668333392283
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Advice</b>	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Minor</b>	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
<b>Advice</b>	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

<b>MOT #11</b>	2019-09-20 09:25
<b>MOT test number</b>	790451116327
<b>Result</b>	✗ Failed
<b>Advice</b>	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Minor</b>	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
<b>Fail</b>	Windscreen in an unacceptable condition (3.2 (c) (i))
<b>Advice</b>	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Advice</b>	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

<b>MOT #10</b>	2018-10-11 13:29
<b>MOT test number</b>	198272069233
<b>Result</b>	✓ Passed
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #9** 2017-10-13 16:06**MOT test number** 541081730490**Result** ✓ Passed**MOT #8** 2017-10-10 11:21**MOT test number** 762884172926**Result** ✗ Failed**Fail** Nearside Front Front suspension has excessive movement at a suspension ball joint upper hub ball joint (2.5.A.1c)**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** All tyres are worn unevenly on their edges**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #7** 2016-10-10 08:32**MOT test number** 756031452740**Result** ✓ Passed**Advice** Rear tyres worn on both edges**Advice** Engine fault light on**Advice** Scratches on screen but not adversely affecting view to front

**MOT #6**

2016-10-07 10:37

**MOT test number**

721976006093

**Result****✗ Failed****Fail** Nearside Front Lower Front suspension has excessive movement at a suspension ball joint (2.5.A.1c)**Advice** Scratches on screen but not adversely affecting view to front**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Rear tyres worn on both edges**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Rear registration plate insecure In rear window (6.3.1b)**Advice** Engine fault light on**Fail** Registration plate lamp not illuminating the registration plate (1.1.C.1e)**MOT #5**

2015-10-19 14:53

**MOT test number**

791630375931

**Result****✓ Passed****Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4**

2015-10-19 11:44

**MOT test number**

636610714578

**Result****✗ Failed****Fail** Nearside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #3** 2014-05-16 09:00**MOT test number** 567676234103**Result** ✓ Passed

- Advice** Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #2** 2013-05-13 14:25**MOT test number** 839803533165**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #1** 2012-05-11 15:49**MOT test number** 266202432113**Result** ✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-06-24
Last registration	2022-10-19
Complete history	<a href="#">See info</a>



Registration #1	2009-06-24	12 mi
Registration #2	2012-05-11	14.906 mi
Registration #3	2013-05-13	26.404 mi
Registration #4	2014-05-16	36.365 mi
Registration #5	2015-10-19	52.727 mi
Registration #6	2015-10-19	52.727 mi
Registration #7	2016-10-07	64.197 mi
Registration #8	2016-10-10	64.197 mi
Registration #9	2017-10-10	71.922 mi
Registration #10	2017-10-13	71.923 mi
Registration #11	2018-10-13	71.923 mi
Registration #12	2018-10-13	71.923 mi
Registration #13	2018-10-13	71.923 mi
Registration #14	2018-10-13	71.923 mi
Registration #15	2018-10-13	71.923 mi
Registration #16	2018-10-13	71.923 mi
Registration #17	2018-10-13	71.923 mi
Registration #18	2018-10-13	71.923 mi
Registration #19	2018-10-13	71.923 mi

More info >



Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)

Dimensions & weight

Width	1853 mm
Height	1456 mm
Length	4779 mm
Wheel base	2815 mm
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	JBAJ3204064