





report date: 2024-03-28

General information

Make	FIAT
Model	TIPO EASY PLUS
Colour	White
Year of manufacture	2016
Top speed	115 mph
0 - 60 mph	12.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	94 BHP
Max. torque	127 Nm at 4.500 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E



CarCheck.co.uk page 1/12



LL66CFP

report date: 2024-03-28

Internet history

Entry 2

Date 2021-10-26

Pictures 8

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-10-25
Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-01-31
MOT pass rate	50 %
MOT passed	5
Failed MOT tests	5
Total advice items	17
Total items failed	8

MOT #10		2024-01-19 14:16
MOT test	number	822669973282
Result		✓ Passed
Next expi	ry date	2025-01-31
Advice	Front Tyre worn close to legal limit/worn on edge Both front tyres worn	on inner edge (5.2.3 (e))
Advice	Coolant leak	

MOT #9	2024-01-19 09:30
MOT test number	308799876140
Result	X Failed
Advice Coolant leak	
Fail Nearside Side repeater not working (4.4.1 (a) (ii))	
Advice Front Tyre worn close to legal limit/worn on edge Both front tyres worn on in	ner edge (5.2.3 (e))

MOT #8	2023-02-01 17:22
MOT test number	805920621142
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))	
Advice Offside Rear Tyre slightly damaged Sidewall (5.2.3 (d) (ii))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

CarCheck.co.uk page 3/12



MOT #5

LL66CFP

report date: 2024-03-28

MOT #7 2023-01-27 11:54 595623152145 **MOT** test number Result × Failed **Advice** Offside Rear Tyre slightly damaged Sidewall (5.2.3 (d) (ii)) Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Tyre tread depth below requirements of 1.6mm BOTH FRONT (5.2.3 (e)) Fail **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

MOT #6 2022-01-26 15:24 **MOT** test number 584440391239 Result ✓ Passed

2022-01-25 17:31 **MOT** test number 850971122089

Result × Failed

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) Fail

MOT #4 2021-10-22 16:17

MOT test number 776522386114

Result ✓ Passed

CarCheck.co.uk page 4/12



Result

LL66CFP

report date: 2024-03-28

✓ Passed

MOT #3 2021-10-22 16:01

MOT test number 373272690102

Result X Failed

Fail Front Windscreen wiper does not clear the windscreen effectively Both (3.4 (b) (ii))

MOT #2 2020-10-15 15:22

MOT test number 895856738704

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Windscreen wiper blade defective (3.4 (b) (i))

MOT #1 2020-10-15 15:22

MOT test number 515181766646

Result X Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Windscreen wiper blade defective (3.4 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	31 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



LL66CFP

report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



faste since

LL66CFP

report date: 2024-03-28

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this FIAT had different number plates.

More info >

CarCheck.co.uk page 9/12



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2016-10-31
Last registration	2024-01-19
Complete history	See info



Registration #1	2016-10-31	23 mi
Registration #2	2020-10-15	19.459 mi
Registration #3	2020-10-15	19.459 mi
Registration #4	2021-10-22	22.799 mi
Registration #5	2021-10-22	22.799 mi
Registration #6		0.00 44
Registration #7		11.777 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		0.00 44
Registration #11		11.777 mi
Registration #12		0.00 44
Registration #13		10.777 au

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	82%
Children	60%
Pedestrian	62%
Safety systems	57%
Overall rating	68%
Video	see crash video



Dimensions & weight

Width	1792 mm
Height	1495 mm
Length	4368 mm
Wheel base	2638 mm
Kerb weight	1270 kg
Max. allowed weight	1695 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 12/12