



PEUGEOT



VU6IHYZ


report date: 2024-03-28

General information

Make	PEUGEOT
Model	5008 HDI EXCLUSIVE
Colour	Red
Year of manufacture	2011
Top speed	114 mph
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-06-26
Pictures	40
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-23
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	28
Total items failed	6

MOT #16	2023-08-14 08:44
MOT test number	306660578005
Result	✓ Passed
Next expiry date	2024-08-23

MOT #15	2023-08-14 08:44
MOT test number	882861082816
Result	✗ Failed
Pass with rectification	Offside Front Shock absorbers has an excessively worn bush (5.3.2 (c))
Pass with rectification	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Pass with rectification	Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Pass with rectification	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #14	2022-08-24 08:34
MOT test number	758341343912
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Central Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2022-08-24 08:34**MOT test number** 512190998255**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Minor** Central Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))**MOT #12** 2021-07-19 14:00**MOT test number** 688498420296**Result** ✓ Passed**Minor** Stop lamp(s) with a multiple light source up to 1/2 not functioning eye level (4.3.1 (a) (i))**MOT #11** 2021-07-19 11:16**MOT test number** 179834614151**Result** ✗ Failed**MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Small screw in o/s/r tyre**Minor** Stop lamp(s) with a multiple light source up to 1/2 not functioning eye level (4.3.1 (a) (i))**MOT #10** 2020-09-04 13:30**MOT test number** 487130698530**Result** ✓ Passed

**MOT #9** 2020-09-02 14:58**MOT test number** 928279592025**Result** ✗ Failed**MAJOR** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Fluid leak harmful to the environment or a risk to other road users excessive fumes in cabin (8.4.1 (a) (i))**MOT #8** 2019-09-25 08:47**MOT test number** 723499685117**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #7** 2019-09-24 15:00**MOT test number** 175868416569**Result** ✗ Failed**MAJOR** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #6** 2018-09-14 11:15**MOT test number** 274889519504**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2017-09-18 12:03**MOT test number** 714870359235**Result** ✓ Passed**Advice** Nearside Rear back row child seat fitted not allowing full inspection of seat belt**MOT #4** 2016-09-12 11:48**MOT test number** 424770013749**Result** ✓ Passed**MOT #3** 2015-09-21 13:36**MOT test number** 721539504989**Result** ✓ Passed**Advice** Both wipers in poor condition**MOT #2** 2014-09-09 15:44**MOT test number** 908092254223**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2014-09-09 15:44**MOT test number** 647302254201**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
23 August 2024

Tax status	Valid until 1 January
Days left	248
MOT expiry date	23 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-09-28
Last registration	2023-08-14
Complete history	See info



Registration #1	2011-09-28	21 mi
Registration #2	2014-09-09	21.780 mi
Registration #3	2015-09-21	31.992 mi
Registration #4	2016-09-12	39.387 mi
Registration #5	2017-09-18	46.755 mi
Registration #6	2018-09-14	52.927 mi
Registration #7	2019-09-24	61.524 mi
Registration #8	2019-09-25	61.524 mi
Registration #9	2020-09-02	66.558 mi
Registration #10	2020-09-02	66.558 mi
Registration #11	2020-09-02	66.558 mi
Registration #12	2020-09-02	66.558 mi
Registration #13	2020-09-02	66.558 mi
Registration #14	2020-09-02	66.558 mi
Registration #15	2020-09-02	66.558 mi
Registration #16	2020-09-02	66.558 mi
Registration #17	2020-09-02	66.558 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	79%
Pedestrian	37%
Safety systems	97%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2118 mm
Height	1638 mm
Length	4530 mm
Wheel base	2727 mm
Kerb weight	1699 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	JBER3021683