



report date: 2024-03-28

## General information

Make	VAUXHALL
Model	AGILA S ECOFLEX
Colour	Blue
Year of manufacture	2010
Top speed	99 mph
0 - 60 mph	14.7 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	64 BHP
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	45.6 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-08-18
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk



## MOT history

MOT expiry date	2024-08-01
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	23
Total items failed	6

MOT #15 2023-07-21 09:51

MOT test number 209294392468

Result ✓ Passed

Next expiry date 2024-08-01

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Minor** Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #14 2022-07-29 15:34

MOT test number 969130596639

Result ✓ Passed

- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Minor** Offside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #13 2021-08-02 14:16

MOT test number 669662708073

Result ✓ Passed

**MOT #12** 2021-07-29 15:07**MOT test number** 203294258595**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #11** 2020-07-31 14:10**MOT test number** 762848309533**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Tyre slightly damaged/cracking or perishing inbetween tread. (5.2.3 (d) (ii))**MOT #10** 2020-07-29 09:10**MOT test number** 786499465710**Result** ✗ Failed**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing inbetween tread. (5.2.3 (d) (ii))**Advice** Child Seat fitted not allowing full inspection of adult belt**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #9** 2019-05-29 15:43**MOT test number** 986613922572**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt

**MOT #8** 2019-05-21 09:43**MOT test number** 711975842349**Result** ✗ Failed**Advice** Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Front Sub-frame fractured (5.3.3 (b) (ii))**MOT #7** 2018-05-15 09:14**MOT test number** 160559703877**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Front Inner Brake pad(s) wearing thin (3.5.1g)**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Rear handbrake efficiency only just meets legal requirements of 16%.indicating adjustment or repair maybe necessary.**Advice** Offside Front Suspension arm repaired, but not inappropriately securing nut/bolt not tightened to full capacity.threads corroded/will need further attention/repair.nut & bolt not insecure or excessively loose. (2.4.A.2)**MOT #6** 2017-05-19 09:13**MOT test number** 292055765575**Result** ✓ Passed**Advice** Nearside Rear Brake pipe slightly corroded where it clips on to subframe (3.6.B.2c)**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Brake pipe slightly corroded where it clips on to subframe. (3.6.B.2c)**MOT #5** 2016-05-26 09:07**MOT test number** 489034111960**Result** ✓ Passed

**MOT #4** 2016-05-25 12:55**MOT test number** 296276025304**Result** ✗ Failed**Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**MOT #3** 2015-08-14 10:20**MOT test number** 645546625267**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #2** 2014-08-28 14:41**MOT test number** 335490244275**Result** ✓ Passed**MOT #1** 2013-09-13 13:56**MOT test number** 898836553254**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
1 August 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	156
<b>MOT expiry date</b>	1 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 YD60KXU
Plate since	2019-06-28
Current registration	 YD60KXU
Plate since	2019-06-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-09-29
Last registration	2023-07-21
Complete history	<a href="#">See info</a>



Registration #1	2010-09-29	20 mi
Registration #2	2013-09-13	27.792 mi
Registration #3	2014-08-28	37.575 mi
Registration #4	2015-08-14	50.256 mi
Registration #5	2016-05-25	57.377 mi
Registration #6	2016-05-26	57.377 mi
Registration #7	2017-05-19	64.824 mi
Registration #8	2018-05-15	71.954 mi
Registration #9	2019-05-21	78.703 mi
Registration #10	2020-05-21	85.377 mi
Registration #11	2021-05-21	92.377 mi
Registration #12	2022-05-21	99.377 mi
Registration #13	2023-05-21	106.377 mi
Registration #14	2024-05-21	113.377 mi
Registration #15	2025-05-21	120.377 mi
Registration #16	2026-05-21	127.377 mi
Registration #17	2027-05-21	134.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	975 kg
Max. allowed weight	1485 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	1089195